GILES CHEMICAL CORPORATION							
COMPANY PROCEDURE							
Standard Operating Procedure	Page		1 of 2	Revision	:		
Starton of Stating 11000 doi:	ruge .		1 01 2	Date	:	02/12/07	
Author: Maintenance Title: Loc	Title: Lock Out Tag Out Screener						

Safety: All safety glasses and appropriate safety apparel is to be worn at all times.

Purpose or Objective: The purpose of this procedure is to define the process required to lock out the Screener at the main facility at 102 Commerce Street

Procedure: The proper process to lockout Screener is as follows:

- 1. Notify all affected employees that the machine is being taken out of production.
- 2. Locate disconnect to screen at MCC #2
- 3. Turn disconnect to the off position on MCC #2
- 4. Install multi lockout device
- 5. *ID tag with name, date and time*
- 6. Test start switch to screener to ensure screener is not operational

Proper procedure to return equipment to operation:

- 1. Make sure all work is complete and all tools and maintenance equipment has been removed from the machine.
- 2. Notify all affected employees that equipment is about to be put back into service.
- 3. Remove Id tag with name, date and time
- 4. Remove padlock-multi locking device from disconnect
- 5. Turn disconnect handle to the on position
- 6. Ensure that Screener is operating properly and available to be returned to production

GILES CHEMICAL CORPORATION							
COMPANY PROCEDURE							
Standard Operating Procedure	Page		2 of 2	Revision	:		
Standard Operating Procedure	1 agc	gc . 2012		Date	:	02/12/07	
Author: Maintenance Title: Lock	Title: Lock Out Tag Out Screener						

TRAINING DOCUMENTATION

EMPLOYEE	TITLE	SIGNATURE	DATE
1	***************************************		
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			