

# GILES CHEMICAL COMPANY POLICY / PROCEDURE

PH Probe Calibration for Sewer Probe (Asset Tag #10035)

Page :

1 of 5

Revision : Date : 05/

00 05/11/09

Author: Robert Willis/Jody Conner

Job Specific

## **Safety:**

All safety glasses and appropriate safety apparel is to be worn at all times. This includes wearing the appropriate protection for working at heights above six feet.

## **Purpose:**

To outline steps to calibrate the PH probe located in the waste line (Asset Tag #10035) at the rear of the plant near the water recovery system

### **Procedure:**

This calibration procedure should be conducted during the morning and checked in the afternoon if a new probe was installed.

- 1. Equipment:
  - a. 3 250 ml Plastic Beakers
  - b. Calibration buffers pH 4, and 7
  - c. Deionized water
  - d. pH meter with electrode
  - e. wipes or tissue
- 2. Set-up and procedure
  - a. Pour buffers and water in the containers
  - b. After removing the reservoir cover, remove the probe from the holder, clean with Deionized water and wipe dry with tissue.



c. Place in 4 buffer and observe the reading.



d. Press the Calibrate button on the controller box.



# GILES CHEMICAL COMPANY POLICY / PROCEDURE

PH Probe Calibration for Sewer Probe (Asset Tag | Page

#10035)

Robert Willis/Jody Conner

Job Specific

2 of 5

Revision : Date :

00 05/11/09



Author:

- e. "0000" should appear in the screen. The first 0 is blinking
- f. Press the up arrow to enter 1, then press horizontal arrow, the next 0 blinks, press the up arrow again and the readout should now show "1100", now press enter.
- g. Cal-1 appears on the screen. Since the probe is in pH 4 buffer already just press enter.
- h. The meter should read the buffer for pH and mv after completing the process the meter will show Cal-2



i. Remove the probe from the pH 4 buffer solution, rinse with clean DI water, dry with a tissue, then place in pH 7 buffer.



j. Press enter then reads the pH and mv. After completing the test, the slope will appear on the screen. 90% and above is acceptable. 85 to 89% must discuss with Technical. Below 85% troubleshoot the system and replace the probe.



- k. After successfully calibrating press enter two times.
- 1. Observe the reading in the buffer solution.



# **GILES CHEMICAL**

COMPANY POLICY / PROCEDURE
PH Probe Calibration for Sewer Probe (Asset Tag #10035)

Page: 3 of 5

Revision Date

00 05/11/09

Author:

Robert Willis/Jody Conner

Job Specific



m. Remove probe from buffer solution and rinse with DI water.



- n. Insert the probe back in the holder and check pH reading against the pH paper.
- Conduct this calibration procedure at least monthly, or more frequently if needed.



## GILES CHEMICAL

COMPANY POLICY / PROCEDURE

PH Probe Calibration for Sewer Probe (Asset Tag
#10035)

Page: 4 of 5

Revision : Date :

00 05/11/09

Author:

Robert Willis/Jody Conner

Job Specific

## TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				
2				
3				
4				
5				
6				
7				
8				
9	910111011101110111111111111111111111111			
10				
11				
12				
13				
14				
15				
16				
17				
18				



## **GILES CHEMICAL**

COMPANY POLICY / PROCEDURE

PH Probe Calibration for Sewer Probe (Asset Tag
#10035)

Page: 5 of 5

Revision : Date :

00 05/11/09

Robert Willis/Jody Conner Author:

Job Specific

Revision Number	Revision Date	Revision Author	Revision Description
00	05/12/09	RW/JC	New Document