SPECIAL CUSTOMER REQUIREMENTS #12

TO: PRODUCTION

FROM: SALES

DATE: December 1, 2003

Date Ammended: November 8, 2004

The following customer has special production and/or shipping requirements:

CUSTOMER: Pelican Chemical

1300 Scott Street Missoula, MT 59802

PRODUCTION REQUIREMENTS: OVERS ONLY:

Product must be completely and thoroughly dry. If necessary, overdry product slightly. 2200 lbs. Per bag. Staple label to bag seam stating 2200

lb. net. wt. Do not use liner in

supersack!!!!!!

SHIPPING REQUIREMENTS: Check bags before loading to insure there

are no hard or lumpy bags. O.K. to put single in nose and single somewhere in middle of load. DO NOT put single on rear.