GILES CHEMICAL CORPORATION							
COMPANY PROCEDURE							
Standard Operating Procedure	Page	:	1 of 2	Revision Date	:	02/12/07	
Author: Maintenance Title: Lock	Title: Lock Out Tag Out Conveyor #2						

Safety: All safety glasses and appropriate safety apparel is to be worn at all times.

Purpose or Objective: The purpose of this procedure is to define the process required to lock out the Conveyor #2 in the Repack facility

Procedure: *The proper process to lockout the Conveyor #2 is as follows:*

- 1. Notify all affected employees that the machine is being taken out of production.
- 2. Turn electrical disconnect off and install pad lock-multi locking device with id tag
- 3. *ID tag must contain name, date and time lock out occurs.*
- 4. Test the machine to ensure that it is locked out and will not start

Proper procedure to return equipment to operation:

- 1. Make sure all work is complete and all tools and maintenance equipment has been removed from the machine.
- 2. Notify all affected employees that equipment is about to be put back into service.
- 3. Remove ID tag with name, date, and time.
- 4. Remove multi-locking device with padlock
- 5. Return disconnect to the on position
- 6. Check to ensure Conveyor #2 is operating properly.

.

GILES CHEMICAL CORPORATION							
COMPANY PROCEDURE							
Standard Operating Procedure	Page	:	2 of 2	Revision	:	02/12/07	
Author: Maintenance Title: Lock	Title: Lock Out Tag Out Conveyor #2						

TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				нининин
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				