

GILES CHEMI	ICAL
COMPANY POLICY / I	PROCEDURE

Process Temperatures

Page :

1 OF 3

Revision : Date : 10/22/2008 07/18/2006

Author: Patrick Owen

Effectiveness Procedure

## **Personnel responsible:**

Lead Operator, Material Handler, Assistant Operator

### Safety:

Safety glasses and safety shoes

#### **Procedure:**

- 1. The Dryer Salt Temperature needs to stay within the range posted on the Documentation System announcement screen. If you are running Arch and the temperature cannot be kept in range, pull off and make another product.
- 2. The temperature range can vary with the season, temperature, and production rate but will be posted on the Documentation Screen.
- 3. If the Crystallizer Temperature goes above 35 C, the Crystallizer needs to be slowed down in order to cool it off. If it cannot be cooled below 35 C, it needs to be stopped until it can be cooled down.



GILES CHEMICAL							
COMPANY POLICY / PROCEDURE							
	Process Temperatures	Page :	2 OF 3	Revision Date	:	10/22/2008 07/18/2006	
Author:	hor: Patrick Owen Effectiveness Procedure						

# TRAINING DOCUMENTATION

E	MPLOYEE	TITLE	SIGNATURE	DATE
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				



# GILES CHEMICAL COMPANY POLICY / PROCEDURE

Process Temperatures

Page :

3 OF 3

Revision : Date : 10/22/2008 07/18/2006

Author: Patrick Owen

Effectiveness Procedure

Revision Number	Revision Date	Revision Author	Revision Description
00	7/18/2006	PLO	Original Document
01	10/22/2008	PLO	Updated for new format, dryer range on doc system, crystallizer range extended to 35C