

## Personnel responsible:

1. Lead Operator

#### Safety:

Safety shoes and safety glasses are required when working in the plant.

### **Summary:**

It is important to check the Mother Liquor coming from the Centrifuge for large crystals every day. Large crystals indicate a hole in the Centrifuge basket.

#### **Procedure:**

- 1. Locate the Centrifuge Sieve and carry it back to the Mother Liquor pot.
- 2. Place the sieve under the outflow pipe from the Centrifuge.
- 3. Slowly count to 10. The Mother Liquor will splash around, but hold the sieve under the flow.
- 4. Remove the sieve and inspect the contents.
- 5. Only a slight skim of small crystals should be in the sieve.
- 6. Large amounts of crystal or very large crystals indicate that a hole is in the Centrifuge basket.
- 7. Report the suspected hole on the shift log.



GILES CHEMICAL
<b>COMPANY PROCEDURE</b>

Checking the Centrifuge Basket

Page :

2 of 3

Revision : Date : 00 11/1/2010

Author:

Patrick Owen

Job Specific

# TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				



Author:

# GILES CHEMICAL COMPANY PROCEDURE

Revision Date 00 11/1/2010

Checking the Centrifuge Basket Page :

Patrick Owen Job Specific

Revision Number	Revision Date	Revision Author	Revision Description
00	11/1/2010	PLO	Original document