## **SPECIAL CUSTOMER REQUIREMENTS # 52**

TO: PRODUCTION

FROM: SALES

DATE: 1/19/06: **NEW** 

5/17/06: **NEW\*\*** 

The following customer has special production and/or shipping requirements:

## **CUSTOMER:**

OCI CHEMICAL CORP. 1455 RED HAT ROAD, NW DECATUR, AL 35603

## PRODUCTION REQUIREMENTS:

- 1. USE LINERS IN SUPER SACKS\*\*
- 2. SCREEN OUT DUST\*\*
- 3. LOWER TEMPERATURE\*\*
- 4. MAKE SURE BOTTOM SPOUT IS TIED\*\*

## SHIPPING REQUIREMENTS:

- 1. CUSTOMER MUST RECEIVE COA PRIOR TO SHIPPING THE PRODUCT
- 2. PLANT MANAGER MUST ALLOTT SUPER SACKS AHEAD OF TIME FOR THIS CUSTOMER.
- 3. PLANT MANAGER MUST BE AWARE OF SHIPMENT IN ADVANCE