Special Customer Requirement

(Production and Shipping requirements)

#210

Customer(s):

Arcale
Attn: Receiving Dept.
1600 Laframboise, Local 104
St. Hacinthe, PQ J2S 2J3

Recochem, Inc 129 East Drive Brampton, ON L6T 1BS

Certified Packaging

Cannot ship early! May cut 1 but no more pallets if needed

if needed			
et: <u>U-50</u>			
Tech Grade		d	
Screened 20/6	0		
☐ - Take Samples	- One from first pallet, one from #9 and one	from #18 – each with ti	
tion / Packaging			
Type of Film -	Giles USP 50 lb Film	Weight per Bag	50 lbs
Number of Bags pe	r pallet 49 Pallet Configuration	$7x\overline{7}$	
Type of Sacks -		Weight per Bag	
Shrink Wrap	- Date, Time & Lot # on each Bag		al each pallet
☐ - Liners Required - ☐ - Bottom Tie Grommets ☐ - Super sack Tags			_
		ck up number supplied	by customer
- Stickers Requi	·		
Only one lot number per load All print on bags must be legible PO on all paper work. Check with CSR before early shipment			shipment
ıg:			
□ General - Load according to Giles loading chart and quantity on Bill of Lading			
Air Bags	- Double Wrap - Corner Boar	rds	
A	Certificate of Analysis must be provided		before loading
n History:	vates on COA must be in the following format. The	EAR, MONTH, DAT	
Date	Change		
06/20/06	<u> </u>		
12/11/08			
01/12/12	Added "Standard Material" Placards and Sampling		
	□ - Tech Grade □ - Screened 20/6 □ - Screened 20/6 □ - Screened 20/6 □ - Take Samples tion / Packaging Type of Film - Number of Bags per Type of Sacks - □ - Shrink Wrap □ - Liners Require □ - Placards or Tat □ - Stickers Require □ - Other Require □ - Air Bags □ - Must have Quarter □ - Other - □ - History: □ Date □ 06/20/06	Tech Grade	Tech Grade