

### GILES CHEMICAL ~ PREMIER MAGNESIA

**Company Procedure** 

Title: Film Check Number: Q12-PR-100-022
Owner: Louis Martin Revision: 1

Effective Date: 09/10/12 Page: 1 of 3



# 1.0 Purpose

1.1 To describe the process for approval of incoming film for Giles Chemical Products.

## 2.0 Scope

2.1 This procedure is to be performed anytime there is incoming film to Giles Chemical in the Manufacturing area.

### 3.0 Responsibility

3.1 Quality Associate is responsible for inspecting all incoming film.

### **4.0 Safety Considerations**

4.1 Steel-toed shoes and safety glasses are required while on production floor. Safety glasses are required for lab work. Gloves are required when handling the Acue Dyne Test marker. Safety is a consideration of employment. Employees are not authorized to work in an unsafe manner and are prohibited from harming the environment of the facility or community.

### **5.0 Materials/Equipment**

- 5.1 Caliper
- 5.2 Acu Dyne Test Markers #34 or #36
- 5.3 Ruler

### 6.0 Procedure

- 6.1 Production Manager will inform Quality Associate of film arrival.
- 6.2 Quality Associate will inspect the film visually for any defects or printing mistakes before collecting film paperwork from rolls to be tested. A minimum of three rolls from each lot should be tested. At least 2 of the rolls tested must pass all specifications.
- 6.3 Once paperwork is collected, Quality Associate will transport all samples to lab for testing.
- 6.4 Quality Associate will consult appropriate specification sheet and fill in the associated form.
  - 6.4.1 Film Check Tech Film 25 Kg Checklist Q12-PR-100-F022a
  - 6.4.2 Film Check Tech Film 50 Kg Checklist Q12-PR-100-F022b
  - 6.4.3 Film Check USP Film 50 Kg Checklist Q12-PR-100-F022c
  - 6.4.4 Film Check USP Film 16.8 Kg Checklist Q12-PR-100-F022d



### GILES CHEMICAL ~ PREMIER MAGNESIA

**Company Procedure** 

Title: Film Check Number: Q12-PR-100-022

Owner: Louis Martin Revision: 1
Effective Date: 09/10/12 Page: 2 of 3



- 6.5 The caliper is checked to make sure that the measurements are in inches, and that the zero point is set. The zero point is checked by adjusting the caliper until it clicks 3 times. The mil of the film can now be checked.
- 6.6 The mil of the sample film is checked by adjusting the caliper with the film sample in between until it clicks three times. The measurement is then compared to the specification sheet for the film being tested. If it fails, the roll is designated as not approved.
- 6.7 The length and width of the film sample are measured and compared to the specification sheet. If the sample fails either length or width measurements, then the roll is designated as not approved.
- 6.8 Printing of the film is visually checked for color clarity, correct labeling, and correct UPC code per the specification sheet of the roll being tested. If there are misprints or faded color, the roll is designated as not approved.
- 6.9 An Acue Dyne Test marker #34 or #36 is used to test for the non-printable area. The test marker is shaken and then opened. 2 to 3 streaks are drawn across the whole width of the film. The area that is non-printable should bead off. The printable area will now have purple streaks. If either area is incorrect, the roll is designated as not approved.
- 6.10 The perforations on the film are measured and compared to the specification sheet of the roll being tested. If the roll is out of specification, it is designated as not approved.
- 6.11 If any roll is designated as not approved, Quality and Production Manager are informed of non-approved rolls. Quality Associate will then enact Auditing of all rolls in the lot per *Quarantine of Product* Q12-PR-100-012 to determine number of useable rolls. Non approved rolls will be returned to supplier.
- 6.12 Once film has been approved for use, Quality Associate will attach a copy of the completed form to the tested roll, and retain a copy of the completed form and the film sample.
- 6.13 Film retains are to be kept in Quality Lab for three months, and then moved to long term storage until one (1) year past expiry date.

#### 7.0 Reference Documents

7.1 Film Check - Tech Film 25 Kg Checklist Q12-PR-100-F022a



# GILES CHEMICAL ~ PREMIER MAGNESIA

**Company Procedure** 

Title: Film Check Number: Q12-PR-100-022

Owner:Louis MartinRevision:1Effective Date:09/10/12Page:3 of3



7.2 Film Check - Tech Film 50 Kg Checklist Q12-PR-100-F022b

7.3 Film Check - USP Film 50 Kg Checklist Q12-PR-100-F022c

7.4 Film Check - USP Film 16.8 Kg Checklist Q12-PR-100-F022d

7.5 Quarantine of Product Q12-PR-100-012

#### 8.0 Amendment Record

Revision	Revision	Revision	Revision Description
Number	Date	Author	
1	09/10/12	LM	Included associated forms and updated procedure.