## Special Customer Requirement

(Production and Shipping requirements)

**#204** 

## **Customer(s):**

## **USP Grade Customers**

Screened Overs means all salt is screened. All crystals are larger than 12 mesh. Dust and middle cut are screened out.

## **USE 12 MESH SCREEN!**

Run 2 extra pallets when changing from 12 mesh screen back to 16 mesh screen.

Product	San Francisco Bath Salt Co.  U50SO						
Troude			V van c				
	Tech Grade		⊠ - USP C	rade	🗌 - Liqui		
	Screened 20/60	)	Screen	ed 12 MESH	Other	·	
	Take Samples						
Product	ion / Packaging	:					
1	Type of Film -		Giles US	P 50-lb Filn	ı	Weight per Bag	50-lbs
	Number of Bags per	r pallet	49	Pallet Con	figuration	7 per layer	X 7 layers
1	Type of Sacks -				Weight per Bag		
					_ Number and Ir	nitial each pallet	
	☐ - Liners Required - ☐ - Bottom Tie Grommets ☐ - Super sack Tags						
	□ Placards or Tags Required - "SCREENED OVERS"						
	Stickers Required -						
	Other Requirements -						
Shippin	a•						
Shipping:							
	- Air Bags - Double Wrap - Corner Boards -						
	- Must have Quality Approval before loading - Must have Management Approval before loading						
	- Other -						
Revision	History:						
	Date Change						
	12/22/09 San Francisco Bath Salt Co.						