GILES CHEMICAL CORPORATION COMPANY PROCEDURE POUCH MACHINE STARTUP Page : 1 of 1 Date : Revision : 12/2/06 Revision : 12/2/06

Objective

Inform the operators of the correct procedure to start production on the pouch machine.

Scope

PSG LEE RP-84T/Z (Pouch Machine)

Responsibility

Machine Operator, Repack Manager, Maintenance, Material Handlers

Procedure

Warm-Up

- 1. Make sure the air compressor is on. (See **Morning Duties**)
- 2. Locate the scale control panel. Turn the red knob until it comes out.
- 3. Press the green "Power On" button. Wait until it lights up.
- 4. Check and make sure there is salt in the hopper.
- 5. Switch the black knob on the small silver box (located on the front wall of the plant) to "P".
- 6. Press the red "Start/Stop" button for each scale. Make sure the corner lights up.
- 7. Locate the control panel for the pouch machine. Turn the red knob on the control panel until it comes out.
- 8. Press the "Power On" button.
- 9. Press 1, 1, 1, 1 and then "Enter" on the touchscreen.
- 10. Press "Summary Report" on the touchscreen.

Start of Production

- 11. Make sure all of the conveyors and screws are started. (See Morning Duties)
- 12. Press the "Drive" button. Wait until it lights up.
- 13. Turn the "Bag Supply" switch from "Off" to "On".