

GILES CHEMICAL ~ PREMIER MAGNESIA

Company Procedure

Title: Daily Clean Up for Manual Lines

Owner: Mary Masters

Number: R12-PR-100-018

Revision: 0

Effective Date: 01/08/13 Page: 1 of 2



1.0 Purpose

1.1 The purpose of this procedure is to ensure the manual lines are cleaned on a daily basis in the Repackaging Facility at Giles Chemical.

2.0 Scope

2.1 Then manual lines are to be cleaned when the machine is shut down. This procedure applies to all manual line machines.

3.0 Responsibility

3.1 All employees working on manual lines are responsible for daily clean up. The shift Production Supervisor is responsible for making sure all cleaning is done properly and documented.

4.0 Definitions

4.1 N/A

5.0 Safety Considerations

- 5.1 Proper Personal Protective Equipment for the Repackaging Facility is required; steel toed shoes, safety glasses, hair net, and standard safety attire.
- 5.2 Do not get the date coder or any electrical panels wet.

6.0 Materials/Equipment for both manual lines

- 6.1 Air hose
- 6.2 Bucket of hot soapy water
- 6.3 Four cleaning rags
- 6.4 Allen wrenches
- 6.5 Screw driver

7.0 Procedure

- 7.1 Make sure big bell is empty.
- 7.2 Take fill funnel off and wash with hot soapy water.
- 7.3 Take the small auger out and wash with hot soapy water.
- 7.4 Take collar off located at the bottom of the big bell and wash with hot soapy water.



GILES CHEMICAL ~ PREMIER MAGNESIA

Company Procedure

Title: Daily Clean Up for Manual Lines Number: R12-PR-100-018

Owner: Mary Masters Revision: 0
Effective Date: 01/08/13 Page: 2 of 2



- 7.5 Place the fill funnel, small auger and collar on the table to air dry.
- 7.6 Clean fill table with hot soapy water and dry with dry rag.
- 7.7 Open sealer by loosening the two thumb screws.
- 7.8 Take the guide plates off each end.
- 7.9 Using the air hose blow all salt and debris out.
- 7.10 Wash the sealer with hot soapy water and dry with the air hose.
- 7.11 Check all belts and guides to assure they are in good condition.
- 7.12 Clean sealer conveyor belt with hot soapy water and dry with the air hose.
- 7.13 Wash packing table with hot soapy water and dry with dry rag.
- 7.14 With a damp rag wipe taper down and change both tape rolls if needed.
- 7.15 Add ink to date coder ink pad if needed.
- 7.16 When clean up is complete, the shift Production Supervisor must inspect all areas of the machine and sign *Daily Clean Up for Manual Lines* R12-PR-100-F018.

8.0 Reference Documents

8.1 Daily Clean Up for Manual Lines R12-PR-100-F018

9.0 Amendment Record

| Revision | Revision | Revision | Revision Description |
|----------|----------|----------|----------------------|
| Number | Date | Author | |
| 0 | 01/08/13 | MM | New Document |