GILES CHEMICAL CORPORATION								
COMPANY PROCEDURE								
Standard Operating Procedure	Page	:	1 of 2	Revision	:	02/12/07		
Author: Maintenance Title: Lock Out Tag Out Flexcon #1 CM								

Safety: All safety glasses and appropriate safety apparel is to be worn at all times.

Purpose or Objective: The purpose of this procedure is to define the process required to lock out the Flexcon #1 CM at the Repack facility

Procedure: *The proper process to lockout the Flexcon #1 CM is as follows:*

- 1. Notify all affected employees that the machine is being taken out of production.
- 2. Turn electrical disconnect off and install pad lock-multi locking device with id tag
- 3. ID tag must contain name, date and time lock out occurs.
- 4. Test the machine to ensure that it is locked out and will not start.
- 5. Once work is complete, remove lock out tag out tag and id
- 6. Turn electrical disconnect on.
- 7. Notify all affected employees that the machine is being returned to production

Proper process to return equipment to operation:

- 1. Make sure all work is complete and all tools and maintenance equipment has been removed from the machine.
- 2. Notify all affected employees that equipment is about to be put back into service.
- 3. Remove ID tag with name, date, and time.
- 4. Remove multi-locking device with padlock
- 5. Return disconnect to the on position
- 6. Check to ensure equipment is operating properly.

.

GILES CHEMICAL CORPORATION								
COMPANY PROCEDURE								
Standard Operating Procedure			2 of 2	Revision	:			
Standard Operating Procedure	Page		2 01 2	Date	:	02/12/07		
Author: Maintenance Title: Lock	Title: Lock Out Tag Out Flexcon #1 CM							

TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				
2				
3				
4				
5				
6				
7		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
8				
9				
10				
11				
12				
13		January 1971		
14				
15		101111111111111111111111111111111111111		
16				
17				
18				