GILES CHEMICAL CORPORATION							
COMPANY PROCEDURE							
Standard Operating Procedure	Page	:	1 of 2	Revision: Date:11/06/06			
Author: Stacy Howell Title: Sul	Title: Sulfuric Acid Emergency Response						

Safety: Wear all appropriate PPE for the area and job. There is designated PPE for Acid Unloading and Acid testing.

Purpose or Objective: This procedure is to ensure that all safety precautions are taken when handling sulfuric acid.

Sulfuric Acid is a liquid that causes visible destruction and irreversible alteration in human skin or eye tissue. It reacts violently with water or different concentrations of acid. Sulfuric acid visually can look like water therefore; a person should never assume that an unknown liquid is water.

Procedure: Emergency Response for Sulfuric Acid

Skin Contact

- 1) **Immediately** wash under a safety shower for a "Minimum" of 15 minutes while removing contaminated clothing.
- 2) Call for medical help
- 3) Apply ice compress to affected body area. An ice compress decreases the chance of scarring and keeps burn cool.
- 4) Do not apply creams or ointments.

Eye Contact

- 1) Hold eyelids open and wash over an eyewash station for a "Minimum" of 15 minutes.
- 2) Call for help.

Before attempting to help make sure that you know what the dangers are and have on your own PPE. It does not help the situation if you also get burned.

GILES CHEMICAL CORPORATION									
COMPANY PROCEDURE									
Standard Operating Procedure	Page	:	2 of 2	Revision: Date:11/06/06					
Author: Stacy Howell Title: S	Title: Sulfuric Acid Emergency Response								

TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				