

GILES CHEMICAL-GREENDALE COMPANY PROCEDURE

Revision

Date

10/30/2009

1 of 5

Spill Response Plan -Greendale Page :

Paul Teleki Safety

Safety: Proper Personal Protective Equipment for the Area

Author:

Purpose: The purpose of this Spill Response Plan (SRP) is to ensure that Giles Chemical, Greendale is prepared to respond effectively to the release of hazardous materials at the facility. Giles Chemical goal is to protect the general public, Giles employees, and the environment from any release of hazardous material.

Section 1.

The Greendale Plant Manager is responsible for all emergency response measures. The Plant Manager must be familiar with all the locations of hazardous materials at the facility and the characteristics of that material. The Plant Manager has the authority to commit the resources to carry out the SRP.

In the event or a spill emergency, the Plant Manager must immediately be notified. The Plant Manager is responsible for notifying all emergency response agencies, asses potential health and environmental hazards, and take all measures to secure the situation. The Plant Manager is responsible for proper disposal of spill waste, incident investigations, maintenance repairs, and replacement of damaged equipment.

Giles Emergency Contacts:

Plant Manager

Cell: 513-703-2094 Home: 513-738-7254

Safety Manager Cell: 828-400-3729 Home: 828-565-0175

Director of Manufacturing

Cell: 828-400-5765 Home: 828-696-2490

Section 2: Reporting Spills

The Plant Manager or the Safety Manager is responsible for Reporting Spills to County, State, and Federal Regulatory Agencies. All Acid spills above 50 gallons are reportable. A reportable spill has to be reported within 5 minutes of the spill to IDEM and to the National Response Center within 30 days with a written report. The Incident Report can be filled out on-line on the National Response center site under EPA.



GILES CHEMICAL-GREENDALE COMPANY PROCEDURE

Revision

Date

10/30/2009

2 of 5

Spill Response Plan -Greendale Page :

Author: Paul Teleki Safety

(Provided the type of spill is reportable)

Section 3. Emergency Contacts

| Indiana Department of Environmental Management | 1-888-233-7745 |
|--|----------------|
| National Response Center | 1-888-424-8802 |
| • | |
| | |
| | |

Greendale Police Department 911

Greendale Fire Department 1-812-537-7321

Greendale County Sheriff's Department 911

Section 4. Spill Scenario

Operator hooks up a Sulfuric Acid railcar and the connection or the hose is leaking. Spill 50 to 100 gallons of Sulfuric Acid.

Response:

- 1) Stop unloading the acid car. Turn off the valve at the acid car. Plant Manager is only person Responsible for unloading acid at Greendale Facility
- 2) Report to IDEM
- 3) Call the Safety Manager or Director of Manufacturing.
- 4) Contain Spill if possible
- 5) Clean up the spilled material by neutralizing with Lime, make sure the pH raises to 6-7
- 6) Dispose of spill waste according to IDEM rules.

Spill Scenario

Less than reportable amount of Acid is spilled

- 1) Contain Spill, clean-up neutralizing
- 2) Dispose of the material in accordance with EDIM rules.
- 3) Notify the Safety Manager and the Director of Manufacturing

Spill Scenario

Some type of spill occurs after hours. No plant personnel are on the plant site.

- 1) Whom ever observes the spill will call one of the Emergency numbers posted on the Emergency number list on the wall in the front of the building or at the side of the building
- 2) As soon as the Plant Manager shows up the above procedure will be followed.



| GILES CHEMICAL-GREENDALE |
|--------------------------|
| COMPANY PROCEDURE |

00 10/30/2009

Revision

Date

Spill Response Plan -Greendale Page : 3 of 5

Author: Paul Teleki Safety

Section 5. Training

Only the Plant Manager unloads Acid however all appropriate Operators are trained on the Spill Response Plan. Training Records have to be submitted to the Safety Manager. A copy of the training record will be kept by the Plant Manager for Audit purposes.



GILES CHEMICAL-GREENDALE **COMPANY PROCEDURE**

Spill Response Plan -Greendale

Page : 4 of 5

Revision Date

00 10/30/2009

Author: Paul Teleki Safety

| | EMPLOYEE | TITLE | SIGNATURE | DATE |
|----|----------|-------|-----------|------|
| 1 | | | | |
| 2 | | | | |
| 3 | | | | |
| 4 | | | | |
| 5 | | | | |
| 6 | | | | |
| 7 | | | | |
| 8 | | | | |
| 9 | | | | |
| 10 | | | | |
| 11 | | | | |
| 12 | | | | |
| 13 | | | | |
| 14 | | | | |
| 15 | | | | |
| 16 | | | | |
| 17 | | | | |
| 18 | | | | |
| 19 | | | | |
| 20 | | | | |
| 21 | | | | |
| 22 | | | | |
| 23 | | | | |
| 24 | | | | |
| 25 | | | | |
| 26 | | | | |
| 27 | | | | |
| 28 | | | | |
| 29 | | | | |



30

GILES CHEMICAL-GREENDALE COMPANY PROCEDURE

Spill Response Plan -Greendale

Page : 5 of 5 Revision Date

00 10/30/2009

Author: Paul Teleki

Safety

| Revision Number | Revision Date | Revision Author | Revision Description |
|--------------------|------------------|--------------------|----------------------|
| 00 | 10/30/2009 | PT | New Document |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |