

GILES CHEMICAL ~ PREMIER MAGNESIA

Company Procedure

Title: LOTO Circulating Pump Number: S12-PR-200-038

Owner: Robert Willis Revision: 02

Effective Date: 05/21/13 Page: 1 of 2



1.0 Purpose

The purpose of this procedure is to define the process required to lock out the circulating pump at the Manufacturing facility.

2.0 Scope

This procedure applies to all maintenance workers.

3.0 Responsibility

Maintenance and Production

4.0 Safety Considerations

Safety glasses and appropriate safety apparel is to be worn at all times.

Safety is a condition of employment. Employees are not authorized to work in an unsafe manner and are prohibited from harming the environment of the facility or community.

5.0 Materials/Equipment

- Lock
- Tag
- Lock out device

6.0 Procedure

The proper process to lockout the circulating pump is as follows:

- 1. Notify all affected employees that the machine is being taken out of production.
- 2. Place manual box in the stop position
- 3. Install padlock-multi locking device
- 4. ID tag with name, date and time
- 5. Test to see if pump will start

Proper procedure to return equipment to operation:

- 1. Make sure all work is complete and all tools and maintenance equipment has been removed from the machine.
- 2. Notify all affected employees that equipment is about to be put back into service.
- 3. Remove Id tag with name, date and time

Controlled Document



GILES CHEMICAL ~ PREMIER MAGNESIA

Company Procedure

Title: LOTO Circulating Pump Number: S12-PR-200-038

Owner: Robert Willis Revision: 02
Effective Date: 05/21/13 Page: 2 of 2

AGNESIA,

- 4. Remove padlock-multi locking device
- 5. Place manual box in the start position
- 6. Test to see if pump will star

7.0 Reference Documents

N/A

8.0 Change Information

Document review- updated format using new template and numbering system.