

Giles Chemical, a division of Premier Magnesia, LLC. 102 Commerce Street Waynesville, NC 28786 USP Certificate of Analysis

| | 7/7/2011 | | |
|---------------|-------------------------|-------------------|--|
| CUSTOMER: | | | |
| CUST. REF: | | SHIP DATE: | |
| PRODUCT: | Magnesium Sulfate - USP | TRAILER NUMBER: | |
| SHELF LIFE: | 3 Years | BILL OF LADING #: | |
| LOT NUMBER: | 0711 | PO NUMBER # : | |
| SHIPPER: | | MANUFACTURED : | |
| CUST. SERV. : | | | |

I, certify that this material meets all the requirements of the Giles Chemical sales specification and the United States Pharmacopeia 34. Periodic testing has shown the samples to be consistently free of volatile organic impuriities. Giles Chemical manufactured under the guidlines of Good Manufacturing Practices (GMP)

EPSOM SALT, Magnesium Sulfate - Heptahydrate, USP

| METHOD | TEST | LOWER | UPPER | Test Results |
|--------|---------------------------------------|-------|--------|--------------|
| VISUAL | Appearance | ~~ | ~~ | Clear |
| USP34 | Arsenic (PPM) | ~~ | 3.00 | < 3 ppm |
| USP34 | Chloride as CI (%) | ~~ | 0.014 | 0.0017% |
| USP34 | Heavy Metals As Pb (%) | ~~ | 0.001 | < 0.001% |
| USP34 | Ignition Loss (%) | 40.00 | 52.00 | 51.02% |
| USP34 | Iron | ~~ | 20.00 | 0.32 ppm |
| USP34 | MgSO ₄ (Anhydrous wt. %) | 99.00 | 100.50 | 99.46% |
| USP34 | MgSO ₄ (As is basis, %) | 48.30 | 52.00 | 48.54% |
| USP34 | pH 5% Solution | 5.00 | 9.20 | 6.80 |
| USP34 | Selenium (%) | ~~ | 0.003 | < 0.003% |
| USP34 | Nickel (%) | ~~ | ~~ | < 0.005% |
| USP34 | $Mg^{2+}ID$ | | | Present |
| USP34 | SO ₄ ²⁻ ID | | | Present |

| ATTN: | ANALYST: |
|-------|----------|
| | |

SIGNATURE ON FILE