GILES CHEMICAL CORPORATION								
COMPANY PROCEDURE								
Standard Operating Procedure			Page	:	1 of 2	Revision Date	:	02/12/07
	Author: Maintenance Title: Lock Out Tag Out Mud Conveyor Motor (outside collection area)							

**Safety:** All safety glasses and appropriate safety apparel is to be worn at all times.

**Purpose or Objective:** The purpose of this procedure is to define the process required to lock out the Mud Conveyor Motor (outside collection area) in the main facility at 102 Commerce Street

**Procedure:** The proper process to lockout Mud Conveyor Motor (outside collection area) is as follows:

- 1. Notify all affected employees that the machine is being taken out of production.
- 2. Locate disconnect for Mud Conveyor Motor (outside collection area)
- 3. Turn disconnect to the off position
- 4. Install multi lockout device
- 5. *ID tag with name, date and time*
- 6. Test start to ensure that Mud Conveyor Motor (outside collection area) is not operational

Proper procedure to return equipment to operation:

- 1. Make sure all work is complete and all tools and maintenance equipment has been removed from the machine.
- 2. Notify all affected employees that equipment is about to be put back into service.
- 3. Remove ID tag with name, date and time
- 4. Remove multi lockout device
- 5. Turn disconnect to the on position
- 6. Ensure that equipment is operational and available to be returned to production

GILES CHEMICAL CORPORATION						
COMPANY PROCEDURE						
Standard Operating Procedure	Page	:	2 of 2	Revision Date	:	02/12/07
	Author: Maintenance Title: Lock Out Tag Out Mud Conveyor Motor (outside collection area)					

## TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				