GILES CHEMICAL CORPORATION							
COMPANY PROCEDURE							
Standard Operating Procedure	Page	:	1 of 2	Revision Date	:	02/12/07	
Author: Maintenance Title: Lock	Title: Lock Out Tag Out Box Taper #1						

Safety: All safety glasses and appropriate safety apparel is to be worn at all times.

Purpose or Objective: The purpose of this procedure is to define the process required to lock out the Box Taper #1 in repack

Procedure: *The proper process to lockout Box Taper #1 is as follows:*

- 1. Notify all affected employees that the machine is being taken out of production.
- 2. Make sure machine is in the off position
- 3. Unplug cord and install cord end locking device
- 4. Install padlock-multi locking device
- 5. *ID tag with name, date and time*
- 6. Test to see if Box Taper #1 is operational

Proper procedure to return equipment to operation:

- 1. Make sure all work is complete and all tools and maintenance equipment has been removed from the machine.
- 2. Notify all affected employees that equipment is about to be put back into service.
- 3. Remove Id tag with name, date and time
- 4. Remove padlock-multi locking device
- 5. Remove cord end locking device and plug in cord
- 6. *Make sure machine is in the on position and test to make sure machine is operational.*

GILES CHEMICAL CORPORATION									
COMPANY PROCEDURE									
Standard Operating Procedure		Page		2 of 2	Revision	:			
Standard	Operating	griocedure		rage . 2012		2 01 2	Date	:	02/12/07
	Author:	Maintenance	Title: Lock Out Tag Out Box Taper #1						

TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				нининин
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				