

GILES CHEMICAL							
COMPANY PROCEDURE							
	Swabbing Procedure	Page	:	1 of 3	Revision Date	:	00 06/26/2007
Author:	Tina McConnell	Jol	o S	pecific			

Safety: Latex gloves, safety glasses, and standard safety attire for the area. Individuals that are sensitive to scented salt product must inform their supervisor.

Purpose or Objective: The purpose of this procedure is to ensure all equipment has been properly swabbed and there is no cross contamination between swabs.

Procedure:

- 1) Wear latex gloves to ensure no cross contamination of sample.
- 2) Remove clean swap from package.
- 3) When taking sample, ensure to roll swab on each end to ensure entire area of swab contacts surface area of station being swabbed.
- 4) After sample has been taken, place swab in clean zip-lock bag and seal shut.
- 5) Label each zip-lock bag with station that was swabbed.
- 6) After all samples have been taken and all bags are labeled, wash hands thoroughly with soap and water.
- 7) Give bags to Quality Department to be tested.



GILES CHEMICAL
COMPANY PROCEDURE

Swabbing Procedure

Page : 2 of 3

Revision Date 00 06/26/2007

Author: Tina McConnell

Job Specific

TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				



GILES CHEMICAL COMPANY PROCEDURE

Swabbing Procedure

Page : 3 of 3

Revision : 00 Date : 06/26/2007

Author: Tina McConnell

Job Specific

Revision Number	Revision Date	Revision Author	Revision Description
00	06/26/2007	TM	New Document