

GILES CHEMICAL ~ PREMIER MAGNESIA

Company Procedure

Title: Jar Fragrance Mixing

Owner: Kim Williams

Revision: 0

Revision: 0

Effective Date: 08/14/2014 Page: 1 of 2



1.0 Purpose

The purpose of this procedure is to outline mixing process for jar production.

2.0 Scope

This procedure is to be performed any time a blend is made for vapor jar production.

3.0 Responsibility

Trained operator for mixing fragrance: responsible for following this procedure

4.0 Safety Considerations

Safety glasses, steel toe shoes, hair/beard net(s), and smock are required when working in the Repackaging Facility.

Safety is a condition of employment. Employees are not authorized to work in an unsafe manner and are prohibited from harming the environment of the facility or community.

5.0 Materials/Equipment

- Rosemary Mint Jar Fragrance
- Cool Vapor Fragrance
- Camphor
- Menthol Crystals
- 2 blue buckets
- 1 green bucket
- 5 gallon bucket
- Raw Material Mixture Labels
- Blank Batch Mixing Records

6.0 Procedure

Responsibilities

- 1. Break camphor up with air chisel
- 2. Place liquid pump into fragrance barrel and attach air line
- 3. Weigh out camphor place into 5 gallon bucket
- 4. Weigh out menthol crystals place into 5 gallon bucket with camphor
- 5. Weigh out fragrance pour into 5 gallon bucket with camphor and menthol
- 6. Place bucket on blender and turn blender on reverse
- 7. Blend mixture for approximately 45 minutes until completely dissolved



GILES CHEMICAL ~ PREMIER MAGNESIA

Company Procedure

Title: Jar Fragrance Mixing

Owner: Kim Williams

Number: R14-PR-200-047

Revision: 0

Effective Date: 08/14/2014 Page: 2 of 2



8. Fill raw material label out – batch number will be month, day, year, and number of batch (April 25, 2014 3^{rd} batch of the day = 042514-03)

- 9. Fill in batch mixing record with all information
- 10. Pour mixture into smaller bucket and seal lid on
- 11. Place label on lid

7.0 Reference Documents

N/A

8.0 Change Information

New Document