GILES CHEMICAL CORPORATION								
COMPANY PROCEDURE								
Standard Operating Procedure			Page	:	1 of 2	Revision	:	
						Date	:	02/12/07
	Author: Maintenance Title: Lock Out Tag Out Screw Conveyor (centrif-dryer)							

Safety: All safety glasses and appropriate safety apparel is to be worn at all times.

Purpose or Objective: The purpose of this procedure is to define the process required to lock out the Screw conveyor (centrifuge to dryer MCC #3) at the main facility at 102 Commerce Street

Procedure: The proper process to lockout Screw Conveyor is as follows:

- 1. Notify all affected employees that the machine is being taken out of production.
- 2. Locate disconnect for screw conveyor (centrifuge to dryer) on MCC #3
- 3. Turn disconnect for screw conveyor to the off position
- 4. Install multi-locking device on the disconnect
- 5. ID tag with name, date and time
- 6. Test start switch to ensure machine is not operational

Proper procedure to return equipment to operation:

- 1. Make sure all work is complete and all tools and maintenance equipment has been removed from the machine.
- 2. Notify all affected employees that equipment is about to be put back into service.
- 3. Remove Id tag with name, date and time
- 4. Remove padlock-multi locking device from disconnect for screw conveyor (centrifuge to dryer) on MCC #3
- 5. Turn disconnect handle to the on position
- 6. Ensure that screw conveyor is operating properly and available to be returned to production

GILES CHEMICAL CORPORATION							
COMPANY PROCEDURE							
Standard Operating Procedure	Page	:	2 of 2	Revision	:		
Standard Operating Procedure	1 age			Date	:	02/12/07	
Author: Maintenance Title: Lock	Author: Maintenance Title: Lock Out Tag Out Screw Conveyor (centrif-dryer)						

TRAINING DOCUMENTATION

EMPLOYEE	TITLE	SIGNATURE	DATE
1			
2			
3			
4			
5			
6	***************************************		
7			
8			
9			**************************************
10			
11			
12			
13			
14			
15			
16			
17			
18			