GILES CHEMICAL CORPORATION							
COMPANY PROCEDURE							
Standard Operating Procedure	Page	•	1 of 3	Revision	:		
8	1480 . 1010			Date	:	02/12/07	
Author: Maintenance Title: Lock Out Tag Out Automated Pouching Machine							

Safety: All safety glasses and appropriate safety apparel is to be worn at all times.

Purpose or Objective: The purpose of this procedure is to define the process required to lock out the Automated Poucher machine located in our Repack facility on Shelton Street.

Procedure: The proper process to lockout the Automated Poucher Machine is as follows:

- 1. Notify all affected employees that the machine is being taken out of production.
- 2. Use padlock and multi-lock out tool and id tag to secure machine.
- *3. Fill out id tag with name and date/time.*
- 4. Lock out air line to poucher in same manner s item #1 except use valve-locking device to secure air line.
- 5. Test machine to ensure that it will not start after locking out machine.

Proper procedure to return equipment to operation:

- 1. Make sure all work is complete and all tools and maintenance equipment has been removed from the machine.
- 2. Notify all affected employees that equipment is about to be put back into service.
- 3. Remove ID tag with name, date and time from valve locking device
- 4. Remove valve locking device from air line
- 5. Remove ID tag with name date and time from lockout device
- 6. Remove multi locking device with lock from lockout
- 7. Start machine and check for operability
- 8. Ensure that equipment is operational and available to be returned to production

GILES CHEMICAL CORPORATION							
COMPANY PROCEDURE							
Standard Operating Procedure			2 of 3	Revision	:		
		Page :	2 01 3	Date	:	02/12/07	
Author: Maintenance Title: Lock	Title: Lock Out Tag Out Automated Pouching Machine						

TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				

GILES CHEMICAL CORPORATION							
COMPANY PROCEDURE							
Standard Operating Procedure	Page	:	3 of 3	Revision Date	:	02/12/07	
Author: Maintenance Title: Lock Out Tag Out Automated Pouching Machine							

H 1 Q		
10		
	=	