GILES CHEMICAL CORPORATION								
COMPANY PROCEDURE								
Standard Operating Procedure			Page	:	1 of 4	Revision : 11-14-05 Date : 11-14-05		
Author:	Selwyn Scoggin	Title: (00) Bagger Cleaning Procedure						

Personnel responsible: Lead operator

## Safety:

Steel toed shoes, safety glasses, and approved dust mask must be worn while cleaning the bagger.

### **Summary:**

Cleaning the bagger is necessary for reliable performance. The goal is to clean the build up of dust and salt, check for loose or damaged parts, and calibration.

#### **Procedure:**

## A. Preparation

- 1. Continue running the machine until the feed hopper is empty.
- 2. Run one empty bag to clear the last bag of salt.
- 3. Put on safety gear.

#### B. Cleaning

- 1. Use a dead blow hammer to dislodge built up salt from the hopper.
- 2. "Cheat" the bulk hopper solenoid and the weigh bucket solenoid to empty any salt from the scales.
- 3. Go to the back of the machine, cut the film loose from the roll and remove loose film from the machine.
- 4. Use a vacuum cleaner and/or air hose to clean dust from inside the scale housing, outside the scale housing, calibration weights, and the top of bagger.
- 5. Examine the inside of the scale for salt buildup, and remove buildup mechanically or with hot water (only if necessary).
- 6. Release or uncheat the bulk hopper solenoid and the weigh bucket solenoid.
- 7. Check for any loose or damaged parts.
- 8. This completes the cleaning of the scales.
- 9. Open the doors to the bagger and remove any dust or salt residue from all parts of the machine. DO NOT USE WATER.
- 10. Clean the idler and pinch rollers in the back of the machine. Use a damp rag to remove salt buildup from the rollers, and cleaner to remove the ink residue.
- 11. Inspect the machine for broken or damaged parts. Grease all points.
- 12. Cleaning is now complete.

GILES CHEMICAL CORPORATION								
COMPANY PROCEDURE								
Standard Operating Procedure			Page	:	2 of 4	Revision : 11-14-05 Date : 11-14-05		
Author:	Selwyn Scoggin	Title: (00) Bagger Cleaning Procedure						

## C. Calibration

1. Follow calibration procedure.

## D. Restoration

- 1. Rethread film into the machine.
- 2. Run a few empty bags and check for proper alignment and sealing.
- 3. Begin feeding salt into the hopper
- 4. Start with product and observe for proper sealing and weights.

GILES CHEMICAL CORPORATION								
COMPANY PROCEDURE								
Standard Operating Procedure			Page	:	3 of 4	Revision Date	11-14	1-05
Author:	Selwyn Scoggin	Title: (00) Bagger Cleaning Procedure						

# **REVISION HISTORY**

Revision DateRevision NumberRevision Description11/14/0500New Document

GILES CHEMICAL CORPORATION								
COMPANY PROCEDURE								
Standard	Operating Procedure		Page	:	4 of 4	Revision Date	:	11-14-05
Author:	Selwyn Scoggin	Title: (00) Bagger Cleaning Procedure						

# TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				.5
13				
14				
15				
16				
17				
18				
19				
20				