

GILES CHEMICAL ~ PREMIER MAGNESIA

Company Procedure

Title: Quality Approval of Incoming Raw
Number: Q12-PR-100-015

Materials

Owner: Louis Martin

Revision: 0

Effective Date: 08/21/12 Page: 1 of 3



1.0 Purpose

1.1 To describe procedure for granting Quality approval for incoming raw materials.

2.0 Scope

2.1 This procedure applies to incoming raw materials.

3.0 Responsibility

3.1 Quality Associate is responsible for this procedure.

4.0 Safety Considerations

4.1 Special safety considerations are not applicable. Safety is a condition of employment. Employees are not authorized to work in an unsafe manner and are prohibited from harming the environment of the facility or the community.

5.0 Materials/Equipment

5.1 N/A

6.0 Procedure

- 6.1 Open daily the Raw Material Inventory spreadsheet at N:\EngineerOps\RXR & Raw Material\Raw Material.
- 6.2 Identify railcars in which COA's are available.
- 6.3 Review COA's for identified railcars
 - 6.3.1 For <u>Sulfuric Acid COA</u>'s go to N:\EngineerOps\RXR & Raw Material\Raw Material\Acid Paper Work
 - 6.3.2 For MgO COA's go to N:\EngineerOps\RXR & Raw Material\Raw Material\MgO Paper Work
- 6.4 Record information on the following forms:
 - 6.4.1 For <u>Sulfuric Acid</u> use *Quality Approval of Incoming Raw Materials Acid* Q12-PR-100-F015b.



GILES CHEMICAL ~ PREMIER MAGNESIA

Company Procedure

Title: Quality Approval of Incoming Raw
Number: Q12-PR-100-015

Materials

Owner: Louis Martin Revision: 0

Effective Date: 08/21/12 Page: 2 of 3



6.4.2 For MgO use *Quality Approval of Incoming Raw Materials – MgO* Q12-PR-100-F015a.

- 6.5 Check to see if railcar is within control limits and specifications.
 - 6.5.1 Control Limits for Sulfuric Acid are as follows
 - Strength (H₂SO₄%)Lower Control Limit is 92.00%
 - Clarity @ 500NM Lower Control Limit is 80.00%
 - Chlorides Upper Control Limit is 10 ppm
 - Color Upper Control Limit is 40.00
 - Iron Upper Control Limit is 7.50 ppm
 - 6.5.2 Specification Limits for Sulfuric Acid are as follows
 - H₂SO₄ Lower Specification Limit is 93.20%
 - Upper Specification Limit is 95.00%
 - Clarity @ 500NM Lower Specification Limit is 80.00%
 - Chlorides Lower Specification Limit is 0 ppm Upper Specification Limit is 10 ppm
 - Color Upper Specification Limit is 50.00
 - Iron Upper Specification Limit is 50 ppm
 - 6.5.3 Control Limits for MgO are as follows
 - -200 mesh Lower Control Limit is 56.00% Upper Control Limit is 87.00%
 - CaO Upper Control Limit is 4.00%
 - Insoluble Lower Control Limit is 1.60% Upper Control Limit is 2.50%
 - LOI Upper Control Limit is 5.00%
 - MgO Lower Control Limit is 92.50%
 - R₂O₃ Upper Control Limit is 1.20%
 - Sulfur Upper Control Limit is 0.50%
 - Bulk Density Lower Control Limit is 57lbs/cu ft Upper Control Limit is 73lbs/cu ft



GILES CHEMICAL ~ PREMIER MAGNESIA

Company Procedure

Title: Quality Approval of Incoming Raw
Number: Q12-PR-100-015

Materials

Owner: Louis Martin Revision: 0
Effective Date: 08/21/12 Page: 3 of 3



• Reactivity Upper Control Limit is 31 degrees

6.6 If any railcar is out of specification limits, it is automatically rejected.

6.7 If any railcar is out of control limits, it is recorded in O.O.C Railcar

Log book. Log book is reviewed by the Process Engineer, who will determine further action.

7.0 Reference Documents

7.1 Quality Approval of Incoming Raw Materials – MgO Q12-PR-100-F015a

7.2 Quality Approval of Incoming Raw Materials – Acid Q12-PR-100-F015b

8.0 Amendment Record

Revision	Revision	Revision	Revision Description
Number	Date	Author	
0	08/21/12	LM	New Document