GILES CHEMICAL CORPORATION COMPANY PROCEDURE Standard Operating Procedure Page: 1 of 3 Revision : 11-14-05 Date: 11-14-05 Date: 11-14-05

MANUF-BAG-03

Personnel responsible:

Lead operator

Safety:

Steel toed shoes and safety glasses

Summary:

Calibration of the machine is necessary for proper operation. The goal is to provide the customer with consistent weights \pm 0.5 lbs. (on 50-lb bags)

Procedure:

- A. Preparation
- B.
- 1. Stop the bagger and clean the scales. See cleaning procedure.
- 2. Turn scale off (switch directly under screens)
- 3. On the scale screen press the "main" button. (Top Screen)
- 4. Press "config" button
- 5. Press "weight controller" button
- 6. Press "cal" button
- 7. Press "next" button. Check that reading in upper right is 100
- 8. Press "next" button again
- 9. Press "cal-zero" button. Bar graph will advance from left to right, and weight reading will update.
- 10. Press "lower weight" button. Weight reading will increase.
- 11. Press "cal-wgt" button. Bar graph will advance from right to left. Weight reading should read 100.00 + -0.2.
- 12. Press "raise weight" button. Weight reading should go to 0.00 + -0.2. If not repeat steps 8-10.
- 13. Press "done" button.
- 14. Press "main" button.
- 15. Turn scale on (switch directly under screens)
- 16. Scale is calibrated. You can now restart the machine.

| GILES CHEMICAL CORPORATION | | | | | | | | |
|----------------------------|---------------------|--|------|---|--------|------------------|---|----------|
| COMPANY PROCEDURE | | | | | | | | |
| Standard | Operating Procedure | | Page | : | 2 of 3 | Revision Date | : | 11-14-05 |
| Author: | Selwyn Scoggin | Title: (00) Bagger Calibration Procedure | | | | | | |

MANUF-BAG-03

REVISION HISTORY

Revision Date Revision Number Revision Description
11/14/05 00 New Document

| GILES CHEMICAL CORPORATION | | | | | | | |
|----------------------------|---------------------|--|------|---|--------|------------------|----------|
| COMPANY PROCEDURE | | | | | | | |
| Standard | Operating Procedure | | Page | : | 3 of 3 | Revision Date | 11-14-05 |
| Author: | Selwyn Scoggin | Title: (00) Bagger Calibration Procedure | | | | | |

MANUF-BAG-03

TRAINING DOCUMENTATION

| | EMPLOYEE | TITLE | SIGNATURE | DATE |
|----|----------|-------|-----------|------|
| 1 | | | | |
| 2 | | | | |
| 3 | | | | |
| 4 | | | | |
| 5 | | | | |
| 6 | | | | |
| 7 | | | | |
| 8 | | | | |
| 9 | | | | |
| 10 | | | | |
| 11 | | | | |
| 12 | | | | |
| 13 | | | | |
| 14 | | | | |
| 15 | | | | |
| 16 | | | | |
| 17 | | | | |
| 18 | | | | |
| 19 | | | | |
| 20 | | | | |