



# Plant Monitoring & Automated Watering System



# COMPONENTS


SOIL MOISTURE SENSOR & DHT 11 SENSOR



1 - CHANNEL RELAY MODULE & WATER PUMP




ARDUINO UNO R3






# Test Capative v1.2 Sensor



Arduino Uno



SKETCHBOOK



sketch\_jun1a.ino

```
1  #define SOIL_PIN A0
2
3  void setup() {
4      Serial.begin(9600);
5
6      Serial.println("Soil Moisture Sensor Test");
7  }
8
9  void loop() {
10
11      int soilValue = analogRead(SOIL_PIN);
12
13      Serial.print("Soil value: ");
14      Serial.println(soilValue);
15
16      delay(1000);
17  }
```

Output Serial Monitor X

Message (Enter to send message to 'Arduino Uno' on 'COM17')

```
Soil Value: 578
Soil Value: 577
Soil Value: 1023
Soil Value: 231
Soil Value: 74
Soil Value: 37
```

# Test DHT 11





2

```
4 #define DHTTYPE DHT11
```

5

7

```
9 Serial.begin(9600);
```

10

```
12 dht.begin();
```

13 }

14

16

```
18 float temperature = dht.readTemperature();
```

19

```
21 Serial.println("Failed to read from DHT11!");
```

Message (Enter to send message to 'Arduino Uno' on 'COM17')



Humidity: 42.80 %

\_\_\_\_\_

## DHT11 Test

Humidity: 42.80 %

\_\_\_\_\_