







1a Startforth Road, Riverside Park, Middlesbrough TS2 1PT. Tel: 01642 247337 Email: info@he-woolley.co.uk

Emergency Lighting Periodic Inspection and Test

www.fireriskassessment.com	renouic inspect	ivii aii	น เธอเ
Customer Infratoc		4124	
Address Units 8-9 Easter Part, Batum	Order No		
Riverside Ind Est, Middlebrugh TS2	Account Ref	•••••	
Invoice Address if different from above	Invoice No		
I/we hereby certify that the emergency lighting installation at the about in accordance with the schedule below, and to the best of my/our king for the variations, if any, stated in this certificate.	ive premises has been inspe nowledge and belief with BS	cted/tested 5266-1:20	l by me/us 11, except
Annual Inspection and Test 1 Hour Burn 3 Hou	ur Burn Remedial	Work	
RESULTS OF EMERGENCY LIGHT	SERVICE	Yes	No
Regular test results logged		_	
Installation in a satisfactory condition			
Central battery system			_
Self-contained luminaires and signs			
Devices operate on maiins failure		_	
Maintained devices		/	
Non-maintained devices			
Defective devices			
REMEDIAL WORK / PARTS SUPPLIED & FITTED		Quantity	
Twin Spot Light		2	
Bulkhead Light		2	
BEREY LED SPOTUCUT		1	
8w Tube			
NOTE: Because of the possibility of failure of the supply to the not testing, all tests should be undertaken at times of minimal risk. Alto should be made until the batteries are recharged. Comments and Variations, if any, from BS 5266-1:2011 Installation + replacement of emogrand	ernatively, suitable temporar	ry arrangen	ments
Engineer's Signature Customer's Signature	Total VAT		
Print Name			
Position Workship Mange Date 5	14/24 Total		