

1a Startforth Road, Riverside Park, Middlesbrough TS2 1PT. Tel: 01642 247337 Email: info@he-woolley.co.uk www.fireriskassessment.com

BAFE
FIRE SAFETY
REGISTER
Fire Alerm System
Maintenance Only





Certificate of Inspection of Fire Alarm

We being the competent persons responsible for the servicing of the fire alarm system, particulars set out below certify that the said work for which we have been responsible complies to the best of our knowledge and belief with the recommendations of Clause 45 of BS 5839-1:2017 periodic service except for the variations stated in this certificate.

Of Clause 40 of B5 3639-1.2017 periodic service except for the variations stated in this Certification.							
Customer Intrater Units 8-9			Date \\S\12\12\4				
Address Easter Part, Barton Poul			Order No.				
River, de Part Ind Est, Middlebrough, TSZIRY			Account Ref				
Invoice Address if different from above			Invoice No.				
CALL OUT FIRE-ALARM LAGY OF DIVISE DEF							
OFFINIORD OF THE TOTAL OF THE T			LAST SERVICE DATE				
OUT OF HOURS CALL OUT SERVICED 25% 50% 100%							
DDITIONAL HOURS WHOLE SYSTEM SUB SYSTEM			COMPLIANCE YES NO				
VARIATIONS FROM THE RECOMMENDATIONS OF	SPARES	co	NV.	ADDR.	NOTES		
CLAUSE 45:	Panel						
12 MONTHLY SERVICE INTERVALS	Detector - smoke	2					
MISSING DEVICES	Detector - heat						
BELLS NOT TESTED	Detector - base						
	Sounder						
	Call Point	/			The same		
Relevant details of the work carried out and the faults identified	Call Point IP67						
have been entered in the system log book	Battery 1amp-3amp						
During the past 12 months false alarms have occurred	Battery 3amp-7amp						
The above number of false alarms equates to per 100	Battery 12amp-24amp	1					
automatic fire detections per annum.	Spare Glass				The state of the s		
For type M systems, enter N/A.	Aspirator Filter						
To type w systems, enter to	Door Magnet						
Installation of rew devices + existing devices re-connected to Unit 10 Fire Plan parel as per quote 135/P4/2023 Unit 8 Fire Alarm parel disconnected as not required anymore. Units 8,9 +10 all part of same system, Panel located in Unit 10							

- HE Woolley Ltd is not responsible for any installation or alteration made by others at any time to any equipment included in this certificate.
 The certificate is subject to our conditions of sale, copies of which are available upon request.
- It is the client's responsibility to ensure that a weekly test of the alarm system and a monthly check of the emergency lights are performed by the nominated fire/safety officer in order to ensure correct operation. The system log book should be completed accordingly.

Engineer's Signature Print P. HUTCHINSON	Total	
Customer's Signature	VAT	
Print Name Position Date \(\scale=15\) 2124	Total	