### **SECTION 23 05 33 – HEAT TRACING FOR HVAC PIPING**

#### **PART 1 - GENERAL**

### 1.1 RELATED DOCUMENTS

A. Drawings and general provisions of the Contract, including General and Supplementary Conditions and Division 01 Specification Sections, apply to this Section.

### 1.2 SUMMARY

- A. This Section includes heat tracing with the following electric heating cables:
  - 1. Plastic insulated, series resistance.
  - 2. Self-regulating, parallel resistance.
- B. Related Sections include the following:
  - 1. Division 21 Section "Heat Tracing for Fire-Suppression Piping."
  - 2. Division 22 Section "Heat Tracing for Plumbing Piping."

## 1.3 SUBMITTALS

- A. Product Data: Include rated capacities, operating characteristics, furnished specialties, and accessories for each type of product indicated.
  - 1. Schedule heating capacity, length of cable, spacing, and electrical power requirement for each electric heating cable required.
- B. Shop Drawings: For electric heating cable. Include plans, sections, details, and attachments to other work.
  - 1. Wiring Diagrams: Power, signal, and control wiring.
- C. Field quality-control test reports.
- D. Operation and Maintenance Data: For electric heating cables to include in operation and maintenance manuals.
- E. Warranty: Special warranty specified in this Section.

#### 1.4 QUALITY ASSURANCE

A. Electrical Components, Devices, and Accessories: Listed and labeled as defined in NFPA 70, Article 100, by a testing agency acceptable to authorities having jurisdiction, and marked for intended use.

### 1.5 WARRANTY

- A. Special Warranty: Manufacturer's standard form in which manufacturer agrees to repair or replace electric heating cable that fails in materials or workmanship within specified warranty period.
  - 1. Warranty Period: 15 years from date of Substantial Completion.

#### **PART 2 - PRODUCTS**

## 2.1 SELF-REGULATING, PARALLEL-RESISTANCE HEATING CABLES

- A. Available Manufacturers: Subject to compliance with requirements, manufacturers offering products that may be incorporated into the Work include, but are not limited to, the following:
  - 1. BH Thermal Corporation.
  - 2. Chromalox, Inc.; Wiegard Industrial Division; Emerson Electric Company.
  - 3. Delta-Therm Corporation.
  - 4. Easy Heat Inc.
  - 5. Nelson Heat Trace.
  - 6. Pyrotenax; a division of Tyco Thermal Controls.
  - 7. Raychem; a division of Tyco Thermal Controls.
  - 8. Thermon Manufacturing Co.
  - 9. Trasor Corp.
- B. Heating Element: Pair of parallel No. 16 AWG, tinned or nickel-coated stranded copper bus wires embedded in crosslinked conductive polymer core, which varies heat output in response to temperature along its length. Terminate with waterproof, factory-assembled non-heating leads with connectors at one end, and seal the opposite end watertight. Cable shall be capable of crossing over itself once without overheating.
- C. Electrical Insulating Jacket: Flame-retardant polyolefin.
- D. Cable Cover: Tinned-copper braid, and polyolefin outer jacket with UV inhibitor.
- E. Maximum Operating Temperature (Power On): 150 deg F (65 deg C).
- F. Maximum Exposure Temperature (Power Off): 185 deg F (85 deg C).
- G. Maximum Operating Temperature: 300 deg F (150 deg C).

### 2.2 CONTROLS

A. Remote bulb unit with adjustable temperature range from 30 to 50 deg F (minus 1 to plus 10 deg C).

- B. Snap action; open-on-rise, single-pole switch with minimum current rating adequate for connected cable.
- C. Remote bulb on capillary, resistance temperature device, or thermistor for directly sensing pipewall temperature.
- D. Corrosion-resistant, waterproof control enclosure.

### 2.3 ACCESSORIES

- A. Cable Installation Accessories: Fiberglass tape, heat-conductive putty, cable ties, silicone end seals and splice kits, and installation clips all furnished by manufacturer, or as recommended in writing by manufacturer.
- B. Warning Labels: Refer to Division 23 Section "Identification for HVAC Piping and Equipment."
- C. Warning Tape: Continuously printed "Electrical Tracing"; vinyl, at least 3 mils (0.08 mm) thick, and with pressure-sensitive, permanent, waterproof, self-adhesive back.
  - 1. Width for Markers on Pipes with OD, Including Insulation, Less Than 6 Inches (150 mm): <sup>3</sup>/<sub>4</sub> inch (19 mm) minimum.
  - 2. Width for Markers on Pipes with OD, Including Insulation, 6 Inches (150 mm) or Larger: 1-1/2 inches (38 mm) minimum.

#### **PART 3 - EXECUTION**

# 3.1 EXAMINATION

- A. Examine surfaces and substrates to receive electric heating cables for compliance with requirements for installation tolerances and other conditions affecting performance.
  - 1. Ensure surfaces and pipes in contact with electric heating cables are free of burrs and sharp protrusions.
  - 2. Proceed with installation only after unsatisfactory conditions have been corrected.

#### 3.2 INSTALLATION

- A. Install electric heating cable across expansion joints according to manufacturer's written recommendations using slack cable to allow movement without damage to cable.
- B. Install electric heating cables after piping has been tested and before insulation is installed.
- C. Install electric heating cables according to IEEE 515.1.
- D. Install insulation over piping with electric cables according to Division 23 Section "HVAC Insulation."
- E. Install warning tape on piping insulation where piping is equipped with electric heating cables.
- F. Set field-adjustable switches and circuit-breaker trip ranges.

G. Protect installed heating cables, including non-heating leads, from damage.

### 3.3 CONNECTIONS

- A. Ground equipment according to Division 26 Section "Grounding and Bonding for Electrical Systems."
- B. Connect wiring according to Division 26 Section "Low-Voltage Electrical Power Conductors and Cables."

### 3.4 FIELD QUALITY CONTROL

- A. Testing: Perform tests after cable installation but before application of coverings such as insulation, wall or ceiling construction, or concrete.
  - 1. Test cables for electrical continuity and insulation integrity before energizing.
  - 2. Test cables to verify rating and power input. Energize and measure voltage and current simultaneously.
- B. Repeat tests for continuity, insulation resistance, and input power after applying thermal insulation on pipe-mounting cables.
- C. Remove and replace malfunctioning units and retest as specified above.

## **END OF SECTION**