ID	Name	Duration	Start	Finish	Started	Notes		
29	Reliability Engineering - C8 - Sight Flow Indicators on Condensate Drains							
30	Create Asset management /maintenance (ARMS) schedule - C8	4.0d	19 May 2020	22 May 2020	false			
72	Reliability Engineering - C9 - Vo	ent for the A	AlCl3 System					
73	Create Asset management /maintenance (ARMS) schedule - C9	4.0d	19 August 2020	24 August 2020	false			
135	Reliability Engineering - C11 - A	Automatic C	Chlorinator Sump	Controls (1	Level / Density)			
136	Create Asset management /maintenance (ARMS) schedule - C11	4.0d	19 May 2020	22 May 2020	false			
181	Reliability Engineering - C14 - Temperature Indication on Pump out of New Lime Slaker System							
182	Create Asset management /maintenance (ARMS) schedule - C14	4.0d	19 May 2020	22 May 2020	false			



	2101 21101101 0 8					2 tattas 2 tatta 2 a 2 a 3 a 3	
ID	Name	Duration	Start	Finish	Started	Notes	
311	Reliability Engineering - C19 -	Automatic T	ap Blowers - SR	<b>L</b>			
312	Create Asset management /maintenance (ARMS) schedule - C19	4.0d	19 August 2020	24 August 2020	false		
348	Reliability Engineering - C21 - Dual pH Meters in SR Scrubber						
349	Create Asset management /maintenance (ARMS) schedule - C21	4.0d	22 July 2020	27 July 2020	false		
399	Reliability Engineering - C24 -	Dual pH Me	ters in Inc SO2	Scrubbers			
400	Create Asset management /maintenance (ARMS) schedule - C24	4.0d	29 July 2020	03 August 2020	false		
506	Reliability Engineering - C35/SR1 - Density Indication on F-702						
507	Create Asset management /maintenance (ARMS) schedule - C35/SR1	4.0d	19 May 2020	22 May 2020	false		



ID	Name	Duration	Start	Finish	Started	Notes	
585	Reliability Engineering - C38 - V	Water to Sna	ake and Sump Sc	rubbers in	Chlorination	1	
586	Create Asset management /maintenance (ARMS) schedule - C38	4.0d	19 May 2020	22 May 2020	false		
714	Reliability Engineering - O3 - Garo Pump/Fill						
715	Create Asset management /maintenance (ARMS) schedule - O3	4.0d	19 May 2020	22 May 2020	false		
812	Reliability Engineering - O5 - A	cid Scrubbe	r Pump / Fill				
813	Create Asset management /maintenance (ARMS) schedule - O5	4.0d	19 May 2020	22 May 2020	false		
961	Reliability Engineering - O16 - Automatic purge of TiCl4 Flowmeter taps						
962	Create Asset management /maintenance (ARMS) schedule - O16	4.0d	19 August 2020	24 August 2020	false		



ID	Name	Duration	Start	Finish	Started	Notes	
1176	Reliability Engineering - U7 - W	ater Treatn	nent Automation	l			
1177	Create Asset management /maintenance (ARMS) schedule - U7	4.0d	19 May 2020	22 May 2020	false		
1261	Reliability Engineering - U8 - Pl	lant Steam I	Balance				
1262	Create Asset management /maintenance (ARMS) schedule - U8	4.0d	29 July 2020	03 August 2020	false		
1438	Reliability Engineering - U9 - To	reatment Cl	hems Make-up A	utomation (	Chlorine)		
1439	Create Asset management /maintenance (ARMS) schedule - U9	4.0d	19 August 2020	24 August 2020	false		
1490	Reliability Engineering - U20 - Well Water Pressure Control / Remote Monitoring						
1491	Create Asset management /maintenance (ARMS) schedule - U20	4.0d	19 May 2020	22 May 2020	false		
1626	Reliability Engineering - U23 - 1	<b>Instrumenta</b>	tion at Chemical	Storage Ta	nks		



	1101 111011001 0 10					200000 20000 2020 02 00	
ID	Name	Duration	Start	Finish	Started	Notes	
1627	Create Asset management /maintenance (ARMS) schedule - U23	4.0d	19 August 2020	24 August 2020	false		
1718	Reliability Engineering - F241 -	Water Purg	ge for Mulitverte	er Level Rad	ar Eye (L'	Γ-7028)	
1719	Create Asset management /maintenance (ARMS) schedule - F241	4.0d	19 August 2020	24 August 2020	false		
1766	Reliability Engineering - F570 -	Remote Mo	nitoring/Actuati	on of Silo V	alves		
1767	Create Asset management /maintenance (ARMS) schedule - F570	4.0d	19 August 2020	24 August 2020	false		
1834	Reliability Engineering - F580 - Finished Pigment Bin dP Level Instrument Purge						
1835	Create Asset management /maintenance (ARMS) schedule - F580	4.0d	19 August 2020	24 August 2020	false		
1871	Reliability Engineering - F920 -	Continuous	Blending from	F-409 (inclu	des 401 an	d 402)	



ID	Name	Duration	Start	Finish	Started	Notes	
1872	Create Asset management /maintenance (ARMS) schedule - F920	4.0d	19 August 2020	24 August 2020	false		

