

2020-05-19 H2020BC1 Execution Schedule EDIT BY LEHANN

Name: Richard S

Status Date: 30 July 2020

ID	Name	Duration	Start	Finish	% compl	Notes			
Reliability Engineering - C21 - Dual pH Meters in SR Scrubber									
349	Create Asset management /maintenance (ARMS) schedule - C21	4.0d	22 July 2020	27 July 2020	0 %				
Reliab	Reliability Engineering - U8 - Plant Steam Balance								
1262	Create Asset management /maintenance (ARMS) schedule - U8	4.0d	29 July 2020	03 August 2020	0 %				
Reliab	Reliability Engineering - C35/SR1 - Density Indication on F-702								
507	Create Asset management /maintenance (ARMS) schedule - C35/SR1	4.0d	19 May 2020	22 May 2020	0 %				
Reliability Engineering - U7 - Water Treatment Automation									
1177	Create Asset management /maintenance (ARMS) schedule - U7	4.0d	19 May 2020	22 May 2020	0 %				







2020-05-19 H2020BC1 Execution Schedule EDIT BY LEHANN

ID	Name	Duration	Start	Finish	% compl	Notes			
Reliab	Reliability Engineering - C14 - Temperature Indication on Pump out of New Lime Slaker System								
182	Create Asset management /maintenance (ARMS) schedule - C14	4.0d	19 May 2020	22 May 2020	0 %				
Reliability Engineering - O5 - Acid Scrubber Pump / Fill									
813	Create Asset management /maintenance (ARMS) schedule - O5	4.0d	19 May 2020	22 May 2020	0 %				
Reliab	Reliability Engineering - C11 - Automatic Chlorinator Sump Controls (Level / Density)								
136	Create Asset management /maintenance (ARMS) schedule - C11	4.0d	19 May 2020	22 May 2020	0 %				
Reliability Engineering - C24 - Dual pH Meters in Inc SO2 Scrubbers									
400	Create Asset management /maintenance (ARMS) schedule - C24	4.0d	29 July 2020	03 August 202	0 0%				







2020-05-19 H2020BC1 Execution Schedule EDIT BY LEHANN

ID	Name	Duration	Start	Finish	% compl	Notes			
Reliab	Reliability Engineering - O3 - Garo Pump/Fill								
715	Create Asset management /maintenance (ARMS) schedule - O3	4.0d	19 May 2020	22 May 2020	0 %				
Reliab	Reliability Engineering - U20 - Well Water Pressure Control / Remote Monitoring								
1491	Create Asset management /maintenance (ARMS) schedule - U20	4.0d	19 May 2020	22 May 2020	0 %				
Reliab	Reliability Engineering - C38 - Water to Snake and Sump Scrubbers in Chlorination								
586	Create Asset management /maintenance (ARMS) schedule - C38	4.0d	19 May 2020	22 May 2020	0 %				
Reliability Engineering - C8 - Sight Flow Indicators on Condensate Drains									
30	Create Asset management /maintenance (ARMS) schedule - C8	4.0d	19 May 2020	22 May 2020	0 %				



