




5.1 Single crystal deformation as a model

- as the stress increases, the CRSS is occasionally also reached in other, less “favorably” oriented slip systems
- I.e. the dislocations in these slip systems also move and multiply
- Now we have **multiple glide/slip**



At least two types of dislocations on different planes must now intersect and penetrate each other (you already know that this is quite difficult)

The dislocations interfere with each other, now slip takes place on several planes and the surface structure becomes correspondingly complicated

The stress must now be drastically increased in order to “drag” the dislocations apart from each other