

First Notice of Loss and Broker Notice

Claim ID	PROP-B2B-2026-0417
Insured	Nordhafen Precision Parts GmbH
Document type	FNOL / broker notice
Issued by	Kronen Risk Partners GmbH
Document date	12 May 2026
Loss location	Hafenstrasse 18, Building B, 30179 Hannover, Germany

Notice summary

Kronen Risk Partners notified Aegis Mutual Industrial SE of a major property and business interruption loss for Nordhafen Precision Parts GmbH. The notice was based on an email from the insured's CFO, an initial phone call with the plant manager, and photographs sent from a mobile device.

Item	FNOL entry
Date/time received	12 May 2026, 09:18 CEST
Loss date/time stated	12 May 2026 at about 02:38; security log allegedly shows first alarm at 02:27
Premises stated	Hafenstrasse 18A, CNC hall and loading bay
Cause stated by insured	Fire believed to have started at charging station for electric pallet truck. Sprinklers activated.
Operations affected	CNC line 2, anodized stock storage, packing area, server cabinet in mezzanine office
Initial gross estimate	Property damage EUR 1,230,000; BI EUR 800,000; extra expense EUR 55,000

Email extract from insured CFO

From: Miriam Vogel, CFO, Nordhafen Precision Parts GmbH

To: Kronen Risk Partners GmbH

Sent: 12 May 2026, 08:42

Subject: Fire and sprinkler loss - urgent claim opening

"Our loading bay caught fire overnight. The fire brigade shut the site until at least Friday. Smoke entered the CNC hall and water is standing in the packing area. Please notify Aegis today. We cannot ship the May pump-housing order to Volta Pumps and will lose the weekly production window."

The CFO attached six mobile photographs, a preliminary stock export, and a WhatsApp screenshot from the security contractor. The stock export was marked "draft" and did not show salvage or ageing provisions.

Broker notes and requested immediate actions

- Broker requested appointment of loss adjuster and electrical cause expert before debris removal.
- Insured asked whether temporary production at its Bremen subcontractor would be covered as extra expense.
- Broker noted policy condition requiring compliant fixed charging installations for industrial battery equipment.
- Broker could not confirm whether damaged partition walls are tenant improvements or landlord-owned shell property.

Initial claimed values by category

Category	Insured estimate	Basis stated in FNOL	Immediate reservation
Tenant improvements / building works	EUR 410,000	Smoke sealing, walls, doors, loading-bay ceiling panels	Some items may belong to landlord and fall outside insured property.
Stock and work in progress	EUR 520,000	ERP export at standard cost plus 8 percent handling uplift	Salvage and ageing not yet deducted.
Machinery and tooling	EUR 300,000	CNC electronics, measuring bench, forklift charger, compressor dryer	Repair versus replacement unclear.
Business interruption	EUR 800,000	Estimated 8 weeks lost production and delayed shipments	Waiting period and mitigation to be reviewed.
Extra expense	EUR 55,000	Temporary subcontract production, freight, dehumidifiers	Requires prior agreement under policy wording.

FNOL timeline as recorded

Time	Event	Source quality
02:27	Security contractor received technical alarm from Building B sprinkler zone.	WhatsApp screenshot only; not system export.
02:38	CFO says plant manager received phone call from night guard.	Second-hand report.
02:47	Fire brigade incident card opened according to broker phone note.	To be confirmed by official report.
04:10	Fire brigade allowed partial entry to office wing but not loading bay.	Unverified.
07:55	Plant manager halted all shipping and told staff not to enter CNC hall.	Internal instruction.

Coverage notes by broker

The broker stated that Aegis policy AGI-PR-884219 includes contents, tenant improvements, machinery breakdown extension by endorsement, and business interruption. The broker did not attach the full wording. A charging-station warranty and a 48-hour BI waiting period were flagged as likely relevant.

Broker requested that all debris be retained, including the charger, socket, extension lead, pallet truck battery, breaker, and nearby packaging material.