## **Safety Instructions to Operate Stir Casting Machine:**



Always use the below safety accessories while using this machine



High temperature withstanding gloves, preferably full kelvar or asbestos gloves



Foundry Apron



Polycarbonate safety goggles



Leather jeggings



## Do's:

- ✓ Always wear safety accessories such as mask, gloves, googles, apron and shoes
- ✓ Always calculate the volume if mold & load the required quantity of metal/reinforcements in the retort to avoid overflow of melt while pouring into the mold.
- ✓ Align the mold feeder hole and the pouring tube in a straight line.
- ✓ Clean the equipment after each use.

## Don'ts

- X DO NOT LOAD THE RETORT FULLY. This will obstruct the movement of stirrer blade into the retort.
- X DO NOT KEEP THE MELT TEMP. SENSOR INSIDE THE RETORT WHILE STIRRING. This will damage the sensor and the stirrer blade.
- X DO NOT USE THE MACHINE WITHOUT PROPER TRAINING.