One frozen finger13 slot repair | exact continuous triangle / plane sections
Right-source triangles, independently convexified actual proxy meshes, cached 6451-post transforms

Old: one convex hull
Local slot section: x = -3.285978 mm



Repair: three source-driven convex parts
Local slot section: x = -3.285978 mm



6451-post: 13 / 42 at the SAME saved pose

Old: one convex hull; z = 1.036035 mm



6451-post: 13 / 42 at the SAME saved pose

Repair: three source-driven convex parts; z = 1.036035 mm



Right original finger13 STL
Right original finger42 STL
Old finger13 hull
New finger13 parts
Unchanged finger42 hull
OLD convex overlap witness

Qualitative sections only. Source surfaces at this full pose have a 0.229435 mm minimum gap (saved certificate).
The gap is a 3D minimum, not measured in these sections. No global clearance or dynamics PASS is inferred from the figure.
No simulator, FK, contact solve, mesh scan, state injection or new dynamics. Other 75 hand proxies are frozen.