

There is a problem with the current sensors. We forgot that there can be 12V the 0.05 Ohm resistor. So the sensor only works well if I1\_A is on ground, so only for negative currents.

So we define MB as positive pole, and have to reverse the signal from the current sensor (-0.00024 A/bit).