



MICHELIN
Digital Inspection

Fleet Inspection Analysis

for Opicorp,
Opicorp

01/01/2026 - 31/01/2026

POWERED BY  TYRECHECK

Table of Contents

Tyre Inflation	3
Opicorp	4
Durban	4
Inspections	5
Tyre Brands	12
Tyre Sizes	12
Tyre Life	13
Pressure Analysis	13
Pressure Analysis by Axle Type	14
Tread Depth Analysis	15
Tread Depth Analysis by Tyre Life	15
Problem Analysis	16
Recommended Replacements	17
Replace Immediately	17
Carry	17
Drive	17
Replace Within One Month	17
Drive	17
Lift	17
Steer	17
Replace in 2-3 Months	18
Carry	18
Drive	18

Tyre Inflation

Incorrect tyre pressure is one of the most frequent causes of excessive tyre wear and damage. Service manuals produced by vehicle manufacturers, and technical documentation from tyre manufacturers provide information about correct tyre pressure. These values apply to cold tyres, as the inner pressure of the tyre increases during operation.

Tyre pressure of a cold tyre should normally be checked every two weeks, and at most every four weeks. Spare tyres must also be checked.

Underinflation leads to:

- increased flexing, causing the tyre to overheat and possibly fail.
- increased wear, leading to shorter service life.
- higher rolling resistance, leading to increased fuel consumption.
- irregular tread wear.

When checking tyre pressure, be sure to conduct a visual inspection of the tyre for external damage caused by, for example, embedded nails or screws. Missing valve caps and leaky valves should be replaced immediately.

■ Problem

■ Warning

■ Information

Created on: 13/02/2026

By: Mohamed.sha27@outlook.com

POWERED BY



Page 3 of 18

Report Units

	Tread	Pressure	Mileage	Temperature
	mm	Bar	Km	Celsius

Fleet Summary by Vehicle Class

Opicorp

Vehicle Class	No. of Vehicles Inspected	No. of Vehicles in Fleet	% of Vehicles Inspected	No. of Tyres Inspected	No. of Tyres in Fleet	% of Tyres Inspected
Semi-Trailer	8	104	8%	38	844	5%
Tractor Unit	6	105	6%	50	998	5%
TOTAL	14	209	7%	88	1842	5%

Locations Summary by Vehicle Class

Durban

Vehicle Class	No. of Vehicles Inspected	No. of Vehicles in Location	% of Vehicles Inspected	No. of Tyres Inspected	No. of Tyres in Location	% of Tyres Inspected
Dustcart	0	3	0%	0	34	0%
Kalmar	0	1	0%	0	8	0%
Rigid truck	0	1	0%	0	12	0%
Semi-Trailer	8	104	8%	38	844	5%
Tractor Unit	6	105	6%	50	998	5%
Trailer	0	8	0%	0	52	0%
TOTAL	14	222	6%	88	1948	5%



Problem



Warning



Information

Created on: 13/02/2026

By: Mohamed.sha27@outlook.com



Report Units


Tread	Pressure	Mileage	Temperature
mm	Bar	Km	Celsius

Page 4 of 18

Inspections


AC305

Registration No.	CF189006	Location	Durban
		Date/Time	27/01/2026
Make	VOLVO	ODO	
Model	FM 12-400	Hours	
Vehicle Class	Tractor Unit	Inspector	Mohamed.sha27@outlook.com
		Inspection Type	Inspection



AC306

Registration No.	CF188911	Location	Durban
		Date/Time	27/01/2026
Make	VOLVO	ODO	1401039
Model	FM 12-400	Hours	
Vehicle Class	Tractor Unit	Inspector	Mohamed.sha27@outlook.com
		Inspection Type	Inspection



Issues

Pos.	Issue	Action
3LE	Low Tread Depth - Retread	Plan Regrooving
3LE	Pronounced irregular wear	Turn on Rim or Replace

Created on: 13/02/2026

By: Mohamed.sha27@outlook.com


Report Units	Tread	Pressure	Mileage	Temperature
	mm	Bar	Km	Celsius

■ Problem■ Warning■ Information

POWERED BY

AC320

Registration No.	CF179905	Location	Durban
		Date/Time	30/01/2026
Make	VOLVO	ODO	1153799
Model	FM 12-400	Hours	
Vehicle Class	Tractor Unit	Inspector	Mohamed.sha27@outlook.com
		Inspection Type	Inspection




Issues

Pos.	Issue	Action
2LI	Low Tread Depth - New	Plan Regrooving
2RE	Low Tread Depth - New	Plan Regrooving

AC321

Registration No.	CF224970	Location	Durban
		Date/Time	31/01/2026
Make	VOLVO	ODO	15716768
Model	FM 12-400	Hours	
Vehicle Class	Tractor Unit	Inspector	Mohamed.sha27@outlook.com
		Inspection Type	Inspection



Issues

Pos.	Issue	Action
2LE	Urgent Excessive Wear	URGENT Replace
2LI	Urgent Excessive Wear - New	URGENT Dismount for Regrooving
2LI	Tyre at regrooving level	Remove Tyre for Regrooving
2RI	Urgent Excessive Wear	URGENT Replace
2RE	Urgent Excessive Wear	URGENT Replace
3R	Urgent Excessive Wear - Retread	URGENT Dismount for Regrooving
3R	Tyre at regrooving level	Remove Tyre for Regrooving
3R	Pronounced irregular wear	Turn on Rim or Replace

■ Problem ■ Warning ■ Information

Created on: 13/02/2026

By: Mohamed.sha27@outlook.com

POWERED BY

Page 6 of 18


Report Units	Tread	Pressure	Mileage	Temperature
	mm	Bar	Km	Celsius

AC323

Registration No.	CF268276	Location	Durban
		Date/Time	27/01/2026
Make	VOLVO	ODO	9221807
Model	FM 12-400	Hours	
Vehicle Class	Tractor Unit	Inspector	Mohamed.sha27@outlook.com
		Inspection Type	Inspection

Issues

Pos.	Issue	Action
2LE	Urgent Excessive Wear	URGENT Replace
2LI	Urgent Excessive Wear	URGENT Replace
2RI	Urgent Excessive Wear	URGENT Replace
2RE	Urgent Excessive Wear	URGENT Replace




AC367

Registration No.	CF256166	Location	Durban
		Date/Time	30/01/2026
Make	VOLVO	ODO	792577
Model	FM330	Hours	
Vehicle Class	Tractor Unit	Inspector	Mohamed.sha27@outlook.com
		Inspection Type	Inspection

Issues

Pos.	Issue	Action
1L	Urgent Excessive Wear - New	URGENT Dismount for Regrooving
1L	Tyre at regrooving level	Remove Tyre for Regrooving
1R	Urgent Excessive Wear - New	URGENT Dismount for Regrooving
1R	Tyre at regrooving level	Remove Tyre for Regrooving



Created on: 13/02/2026

By: Mohamed.sha27@outlook.com

Problem
Warning
Information

Report Units

Tread	Pressure	Mileage	Temperature
mm	Bar	Km	Celsius

POWERED BY


Page 7 of 18

T305

Registration No.	CF99093	Location	Durban
Date/Time	27/01/2026	ODO	
Make	GENERAL TRAILERS	Hours	
Model	UNKNOWN	Inspector	Mohamed.sha27@outlook.com
Vehicle Class	Semi-Trailer	Inspection Type	Inspection


Issues

Pos.	Issue	Action
1L	Low Tread Depth - New	Plan Regrooving
1R	Low Tread Depth - New	Plan Regrooving
3R	Low Tread Depth - New	Plan Regrooving



T306

Registration No.	CF191580	Location	Durban
Date/Time	27/01/2026	ODO	
Make	GENERAL TRAILERS	Hours	
Model	UNKNOWN	Inspector	Mohamed.sha27@outlook.com
Vehicle Class	Semi-Trailer	Inspection Type	Inspection



Created on: 13/02/2026

By: Mohamed.sha27@outlook.com


■ Problem
■ Warning
■ Information

POWERED BY

Report Units	Tread	Pressure	Mileage	Temperature
	mm	Bar	Km	Celsius


T320

Registration No.	CF179658	Location	Durban
		Date/Time	30/01/2026
Make	FRUEHAUF	ODO	
Model	FRUEHAUF 3	Hours	
Vehicle Class	Semi-Trailer	Inspector	Mohamed.sha27@outlook.com
		Inspection Type	Inspection



T321

Registration No.	CF224953	Location	Durban
		Date/Time	31/01/2026
Make	GENERAL TRAILERS	ODO	1141971
Model	UNKNOWN	Hours	
Vehicle Class	Semi-Trailer	Inspector	Mohamed.sha27@outlook.com
		Inspection Type	Inspection



Issues

Pos.	Issue	Action
1L	Axle Mismatch (Tyre Make)	URGENT Replace
1R	Axle Mismatch (Tyre Make)	URGENT Replace
3R	Low Tread Depth - New	Plan Regrooving

Created on: 13/02/2026

By: Mohamed.sha27@outlook.com


Report Units	Tread	Pressure	Mileage	Temperature
	mm	Bar	Km	Celsius

POWERED BY

Page 9 of 18


T322

Registration No.	CF266412	Location	Durban
Date/Time	27/01/2026	ODO	
Make	GENERAL TRAILERS	Inspector	Mohamed.sha27@outlook.com
Model	UNKNOWN	Inspection Type	VisualInspection
Vehicle Class	Semi-Trailer		




T323

Registration No.	CF270304	Location	Durban
Date/Time	27/01/2026	ODO	6222518
Make	GENERAL TRAILERS	Hours	
Model	UNKNOWN	Inspector	Mohamed.sha27@outlook.com
Vehicle Class	Semi-Trailer	Inspection Type	Inspection



T367

Registration No.	CF171526	Location	Durban
Date/Time	30/01/2026	ODO	792577
Make	GENERAL TRAILERS	Hours	
Model	UNKNOWN	Inspector	Mohamed.sha27@outlook.com
Vehicle Class	Semi-Trailer	Inspection Type	Inspection

**Issues**

Pos.	Issue	Action
1LE	Low Tread Depth - New	Plan Regrooving
1LI	Low Tread Depth - New	Plan Regrooving

■ Problem
 ■ Warning
 ■ Information

Created on: 13/02/2026


By: Mohamed.sha27@outlook.com

Report Units	Tread	Pressure	Mileage	Temperature
	mm	Bar	Km	Celsius

POWERED BY

T376

Registration No.	CF343121	Location	Durban
		Date/Time	27/01/2026
Make	UNI-POWER	ODO	
Model	FLEXIPORTER	Inspector	Mohamed.sha27@outlook.com
Vehicle Class	Semi-Trailer	Inspection Type	Visual Inspection



Created on: 13/02/2026


By: Mohamed.sha27@outlook.com

■ Problem■ Warning■ Information


Report Units

Tread	Pressure	Mileage	Temperature
mm	Bar	Km	Celsius

Tyre Brands



Tyre Sizes


■ Problem

■ Warning

■ Information

Created on: 13/02/2026

By: Mohamed.sha27@outlook.com

POWERED BY




Page 12 of 18


Report Units

	Tread	Pressure	Mileage	Temperature
Report Units	mm	Bar	Km	Celsius

Tyre Life



Pressure Analysis



■ Problem ■ Warning ■ Information

Created on: 13/02/2026

By: Mohamed.sha27@outlook.com

POWERED BY




Page 13 of 18


Report Units	Tread	Pressure	Mileage	Temperature
	mm	Bar	Km	Celsius

Pressure Analysis by Axle Type

Steer Axle




Drive Axle



█ 3. On Target (+/- 5%) (4)
█ 4. Underinflated (> 5%) (2)

█ 2. Overinflated (> 5%) (1)
█ 3. On Target (+/- 5%) (6)
█ 4. Underinflated (> 5%) (5)

2nd Steer/Lift/Carry Axles



Trailer Axle

█ 3. On Target (+/- 5%) (19)
█ 4. Underinflated (> 5%) (5)

█ Problem █ Warning █ Information

Created on: 13/02/2026

By: Mohamed.sha27@outlook.com


POWERED BY 

Page 14 of 18


Report Units

Tread	Pressure	Mileage	Temperature
mm	Bar	Km	Celsius

Tread Depth Analysis



Tread Depth Analysis by Tyre Life



Problem

Warning

Information

Problem Analysis

Issue	Issues Noted During Survey	% of Issues in Survey
Replace Tyre		
Low Tread Depth - New	8	<div style="width: 66.67%;"></div>
Low Tread Depth - Retread	1	<div style="width: 4.17%;"></div>
Urgent Excessive Wear	9	<div style="width: 75%;"></div>
Urgent Excessive Wear - New	3	<div style="width: 25%;"></div>
Urgent Excessive Wear - Retread	1	<div style="width: 4.17%;"></div>
Axle Mismatch (Tyre Make)	2	<div style="width: 16.67%;"></div>
TOTAL	24	80%
Mechanical Anomaly		
Pronounced irregular wear	2	<div style="width: 16.67%;"></div>
TOTAL	2	7%
Wear		
Tyre at regrooving level	4	<div style="width: 33.33%;"></div>
TOTAL	4	13%

■ Problem

■ Warning

■ Information

Created on: 13/02/2026

By: Mohamed.sha27@outlook.com

POWERED BY



Page 16 of 18

Report Units

Tread	Pressure	Mileage	Temperature
mm	Bar	Km	Celsius

Recommended Replacements

RTD in Current Month 2.0
RTD in Next Month 3.0
RTD in Next 2 Months 5.0

Axle Type	Tyre Size	Replace Immediately	Replace Within One Month	Replace in 2-3 Months
Carry	245/70R17.5	0	0	2
Carry	285/70R19.5	2	0	4
Carry	315/80R22.5	0	0	1
Drive	315/70R22.5	7	1	2
Lift	385/55R22.5	0	1	0
Steer	385/65R22.5	0	2	0
TOTAL		9	4	9

Replace Immediately

Carry

Reg. Number	Pos.	Tyre Make	Tyre Size	Tyre Pattern	Tread Depth	Tyre Life	Defects
CF179658	1L	Continental	285/70R19.5	RZ	1.0	New	Urgent Excessive Wear
CF179658	3L	BLACKLION	285/70R19.5	BT165	1.6	New	Urgent Excessive Wear

Drive

Reg. Number	Pos.	Tyre Make	Tyre Size	Tyre Pattern	Tread Depth	Tyre Life	Defects
CF224970	2LE	Michelin	315/70R22.5	X MULTI HD D	1.5	New	Urgent Excessive Wear
CF224970	2RI	Michelin	315/70R22.5	X MULTI HD D	0.2	New	Urgent Excessive Wear
CF224970	2RE	Michelin	315/70R22.5	X MULTI HD D	1.4	New	Urgent Excessive Wear
CF268276	2LE	Michelin	315/70R22.5	X MULTI HD D	1.1	New	Urgent Excessive Wear
CF268276	2LI	Michelin	315/70R22.5	X MULTI HD D	0.0	New	Urgent Excessive Wear
CF268276	2RI	Michelin	315/70R22.5	X MULTI HD D	0.1	New	Urgent Excessive Wear
CF268276	2RE	Michelin	315/70R22.5	X MULTI HD D	0.0	New	Urgent Excessive Wear

Replace Within One Month

Drive

Reg. Number	Pos.	Tyre Make	Tyre Size	Tyre Pattern	Tread Depth	Tyre Life	Defects
CF224970	2LI	Michelin	315/70R22.5	X MULTI HD D	3.0	New	Tyre at regrooving level, Urgent Excessive Wear - New

Lift

Reg. Number	Pos.	Tyre Make	Tyre Size	Tyre Pattern	Tread Depth	Tyre Life	Defects
CF224970	3R	Laurent Retread	385/55R22.5	LR MULTI T R1	2.2	Retread	Pronounced irregular wear, Tyre at regrooving level, Urgent Excessive Wear - Retread

Steer

Reg. Number	Pos.	Tyre Make	Tyre Size	Tyre Pattern	Tread Depth	Tyre Life	Defects
CF256166	1L	BLACKLION	385/65R22.5	BT169	2.6	New	Tyre at regrooving level, Urgent Excessive Wear - New
CF256166	1R	BLACKLION	385/65R22.5	BT169	2.6	New	Tyre at regrooving level, Urgent Excessive Wear - New



Problem



Warning



Information

Created on: 13/02/2026

By: Mohamed.sha27@outlook.com

POWERED BY

Report Units

Tread	Pressure	Mileage	Temperature
mm	Bar	Km	Celsius

Page 17 of 18

Replace in 2-3 Months

Carry

Reg. Number	Pos.	Tyre Make	Tyre Size	Tyre Pattern	Tread Depth	Tyre Life	Defects
CF171526	1LE	Pirelli	245/70R17.5	ST:01	4.4	New	Low Tread Depth - New
CF171526	1LI	Pirelli	245/70R17.5	ST:01	4.9	New	Low Tread Depth - New
CF188911	3LE	Recamic	315/80R22.5	LINE D	4.7	Retread	Low Tread Depth - Retread, Pronounced irregular wear
CF224953	3R	Continental	285/70R19.5	RZ	4.6	New	Low Tread Depth - New
CF99093	1L	Continental	285/70R19.5	RZ	4.7	New	Low Tread Depth - New
CF99093	1R	Continental	285/70R19.5	RZ	4.3	New	Low Tread Depth - New
CF99093	3R	Continental	285/70R19.5	RZ	4.3	New	Low Tread Depth - New

Drive

Reg. Number	Pos.	Tyre Make	Tyre Size	Tyre Pattern	Tread Depth	Tyre Life	Defects
CF179905	2LI	Michelin	315/70R22.5	X LINE ENERGY Z2	5.0	New	Low Tread Depth - New
CF179905	2RE	Michelin	315/70R22.5	X LINE ENERGY Z2	4.5	New	Low Tread Depth - New



Problem



Warning



Information

Created on: 13/02/2026

By: Mohamed.sha27@outlook.com

POWERED
BY

Page 18 of 18

Report Units

Tread	Pressure	Mileage	Temperature
mm	Bar	Km	Celsius