## 孙启翔 241220098

- 3. (1)  $(25.8125)_{10} = (11001.1101)_2 = (31.64)_8 = (19.D)_{16}$ 
  - $(2) \ (101101.011)_2 = (45.375)_{10} = (55.3)_8 = (2D.6)_{16} = (01000101.001101110101)_{8421}$
  - $(3) \ \ (010110010110.0011)_{8421} = (596.3)_{10} = (1001010100.01001...)_2 = (254.4CC...)_{16}$
  - $(4) \ (4E.C)_{16} = (78.75)_{10} = (01001110.1100)_2$
- 4.  $(1) [+0.1001]_{\text{原}} = 0,1001000$ 
  - (2)  $[-0.1001]_{\text{\tiny \bar{\tiny $\beta$}}}=1,1001000$
  - (3) [+1.0]<sub> $\mathbb{R}$ </sub>=0,0000001
  - $(4) [-1.0]_{\mathbb{R}} = 1,0000001$
  - (5)  $[+0.010100]_{\text{\tiny \bar{\tiny $\beta$}}} = 0.0010100$
  - (6)  $[-0.0100]_{\bar{\mathbb{B}}} = 1,0100000$
  - $(7) [+0]_{\mathbb{R}} = 0,0000000$
  - $(8) [-0]_{\mathbb{R}} = 1,00000000$

5.

二进制数	补码	移码
+1001	0,0001001	1,0001001
-1001	1,1110111	0,0001001
+1	0,0000001	1,0000001
-1	1,1111111	0,0000001
+10100	0,0010100	1,0010100
-10100	1,1101100	0,0010100
+0	0,0000000	1,0000000
-0	0,0000000	1,0000000

- 6. (1) x = -11001
  - (2) x = -10000000

- (3) x = 01010010
- (4) x = -101101
- 9. (1) 变为二进制是 1111 1111 1111 1111 0000 0000 0000 0110, 根据补码求真值为(除符号位): 000 0000 0000 0000 1111 1111 1111 1010, 变成十进制是-65530
  - (2) DFFC 变成二进制为: 1011 1111 1111 1010, 求真值并转换成十进制为-(2<sup>14</sup>+6)

  - (4) 2A 变成二进制为 0010 1010, 真值为 42
- 12. (5) 最小负数:  $-2^{2^7} \times (2-2^{-7})$  最大负数:  $-2^{-2^7}$  最小正数:  $2^{-2^7}$  最大正数:  $2^{2^7} \times (2-2^{-7})$

大端机器:

x——地址 100: BE, 地址 101: 00, 地址 102: 00, 地址 103: 00

y----地址 108: 40, 地址 109: F0, 地址 110: 00, 地址 111: 00

i——地址 112: 00, 地址 113: 64

## 小端机器:

x——地址 100: 00, 地址 101: 00, 地址 102: 00, 地址 103: BE

y----地址 108: 00, 地址 109: 00, 地址 110: F0, 地址 111: 40

i——地址 112: 64, 地址 113: 00