



Organización de Computadoras


Ejemplos de instrucciones Curso 2020 Prof. Jorge Runco





























ORG 1000h Var1 dw 1234h	1000H 1001H	34H 12H
	1002H	00Н
MOV AX, Var1	34	
MOV AX, [1000h] AX 12	34	_
MOV BX, 1000h BX 10	00	_
MOV AX, [BX] AX 12	34	
MOV BX, OFFSET Var1 BX 10	00	_
MOV AX, [BX]	34	

