MM_OhmMeter_Test
Wire your Raspberry Pi like the chart below.
Run MM_OhmMeter_Test.py through the Pi Terminal.
Choose resistor value for R(unknown)
Observe reading from program output.

| G11 | G13 | G12 | GND | | Vc |

ADC0832

Connect Vc to this node
to get a reading of
R(unknown)

Rk = 10kΩ   R(unknown)