

Hardness Conversion Chart (HRA-HRC)

Rockwell "A"		
91.8-92.8		
91.5-92.5		
90.5-91.5		
90.2-91.2		
89.8-90.8		
89.0-90.0		
88.5-89.5		
88.0-89.0		
87.5-88.5		
87.0-88.0		
86.0-87.0		
83.0-84.5		
81.5-83.0		

•	•		
Rockwell "C"			
	79.5-81.5		
	79.0-81.0		
	77.0-79.0		
	76.5-79.5		
	75.6-77.6		
	74.0-76.0		
	73.0-75.0		
	72.0-74.0		
	71.0-73.0		
	71.0-72.0		
	69.0-71.0		
	63.0-66.0		
	61.0-63.0		