
a
No external perturbation
b
Alignment force/torque pulse
Task success (%)
100
80
60
40
20
0
Complete sequence
Complete sequence
n = 8 per mode and condition; Wilson 95% intervals
Open loop
Staged feedback
Iterative feedback