

Corrective Action: Next Steps

If the item still exhibits signs of leakage at or after the 1,000 mi (1,600 km) service contact Technical Service for repair approval.