



PAB1156: DAYMAKER® LED FORWARD AUXILIARY LIGHTS UPDATE

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Rev	Revision (Rev) Description
2024-04-19	-	Initial release

Purpose for Parts and Accessories Bulletin

This bulletin inform dealers of the additional components needed to enable fitment of the Daymaker® LED Forward Auxiliary Lights (Part No. 68000340) on 2024 Pan America models.

Vehicles Affected

2024: Pan America S (RA1250S)

Markets Affected

All markets affected.

Summary

The Daymaker® LED Forward Auxiliary Lights (Part No. 68000340) fits 2021 and later Pan America models (RA1250, RA1250S and RA1250SE), that are equipped with an Engine Guard.

It also fits 2014 and later Touring models (except 2023 and later FLHXSE, FLTRXSE and 2024 FLHX, FLTRX and FLTRXSTSE models) and the 2024 CVO Pan America (RA1250SE).

Daymaker® LED Forward Auxiliary Lights (Part No. 68000340) require additional installation kits as follows:

2024 Pan America S (RA1250S) requirements: (Does not require purchase of a switch pack. Lights are controlled through the Instrument Module (IM) menu).

- Quantity (2) of Screw (Part No. 10200924)
- Quantity (2) of Screw (Part No. 10200691)
- Quantity (2) of Auxiliary Lamp Bracket (Part No. 68000403)
- Quantity (2) of Wire Harness Auxiliary Lamp Jumper (Part No. 69203245)
- Quantity (2) of Cable Strap (Part No. 10006)

Pan America and Touring kit requirements:

- 2021-2023 Pan America (RA1250S) and 2021 and later Pan America (RA1250) models require Install Kit (Part No. 68000343).
- 2014 and later Road Glide models require Install Kit (Part No. 68000342).
- All other 2014 and later Touring models require Install Kit (Part No. 68000341).

Questions

Contact Technical Service with any concerns regarding application. Direct all other questions to the Dealer Services Representative.

