



VBUS from USB connector +5V to +3.3V


Output stage?



External DAC and output



Microcontroller and USB



Another USB only for source?

Debug serial can be through an anoother uC, in order to debug the F4 with USB