
Both mesh passages: original peak pressure in material coordinates



Material-coordinate peak-pressure display; linear triangles; grey: outside support; not an instantaneous field.