


Material-coordinate peak-pressure display; linear triangles; grey: outside support; not an instantaneous field.