Company 1	Project Name				Logo 2				
Close Out Sheet									
PSD-HUC-046	MRU Barge Campaign Post Shutdown Phase CRA			Due Date:	2021-03-27				
Activity	Node	Facility		Priority					
			BRG-CPP						
Project Phase Guideword									
MRU Integration Project Post-Shutdown Phase									
Causes									
Inadequate / Incorrect work control procedures for removal and collection of blasting garnet / debris									
Safeguards									
Consequences 1. Unsafe conditions from blasting garnet / debris at work areas and access ways leading to personnel injuries due to slips, trips or falls and asset impact requiring clean-up and repair / rectifications if damaged. 2. Personnel respiratory illness due to inhalation of blasting garnet / debris.									
Taitial siels	Ros	sidual Risk							
Initial risk None	No								
Recommendations/ Actions To confirm methods for containing blasting garnet / debris from impacting platform work area, and to sea. To then update blasting procedure and work pack.									

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed